Technical Service Bulletin



01 MIL on, A8 4.2 FSI, P0491 or P0492 secondary air system bank 1/2 Insufficient flow - Repair Authorization

01 12 65 2030230/2 December 21, 2012. Supersedes Technical Service Bulletin Group 01 number 12-52 dated July 23, 2012 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2011-2012	All	4.2L TFSI

Condition

REVISION HISTORY						
Revision	Date	Purpose				
2	-	Revised header data (corrected VIN range)				
1	8/13/2012	Original Publication				

Engine warning light on

Entries:

- P0491 secondary air system bank 1, Insufficient flow
- P0492 secondary air system bank 2, Insufficient flow

Technical Background

Because of an insufficient vacuum during the catalyst heating phase, the secondary air valves may close prematurely.

Production Solution

Not applicable.

^{© 2012} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Service

Check the complete vacuum system for leaks:

1. Connect a hand vacuum pump with gauge on marked point (Figure 1, arrow).

If the vacuum cannot be kept, check all pipes of the vacuum system and the changeover valves for leaks.




Figure 1. Vacuum system. (A) Operation of left charge-motion control valve. (B) Operation of right charge-motion control valve. (C) Operation of intake manifold control valve. (D) Left secondary air valve. (E) Right secondary air valve. (F) Electric changeover valve for engine thermo management (coolant valve on cylinder head). (1) Vacuum from intake manifold. (2) Vacuum reservoir of cylinder head (0.9 l). (3) Vacuum reservoir in inner V (0.7 l).

© 2012 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prin expressed written permission of the publisher.



Technical Service Bulletin

 Check the connection between changeover valve N489 and vacuum regulator for the cylinder head coolant valve for leaks (Figure 2, arrow).



Figure 2. Vacuum hose not connected.



If no leak or fault is found create a TAC ticket using the Technical Assistance Center System in ElsaWeb, including diagnostic log.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

^{© 2012} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.