

October 03, 2012

48K4 Update - Power Steering Control Unit (NVLW)

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
AC/A7	2012	000927 – 999999		
A6/A7	2013	000001 – 043081	Not Applicable	
A5 A5 Cabriolet S5	2013	000124 - 005453 000297 - 023873 900033 - 901149		
A4/S4	2013	018875 – 120021 000840 – 019774		
allroad	2013	028484 – 120321		

Condition

This Update has been proactively released to prevent the following condition from occurring in the vehicle:

The MIL is on for steering related faults.

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the 48K4 code in the ElsaWeb Campaign/Action Information screen on the day of repair.
- Vehicle must be within the New Vehicle Limited Warranty.
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

Technical Background

On Audi vehicles with electromechanical power steering manufactured within a specific period, an irregularity detected by the diagnosis function can result in an implausible status immediately after the engine is started. This causes the warning lamp for the electromechanical power steering to light up. There is no loss of steering functionality.

Production Solution

New software in the power steering control module (J500) addresses the condition.

© 2012 Audi of America, Inc.

Page 1 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Service



- 1. If the red warning lamp for the steering is displayed in the instrument cluster, the software update must not be performed. Please repair the steering and then perform the software update.
- 2. Follow all instructions in the attached TSB 2011732 00 Software Version Management (SVM), operating instructions.
- 3. Update the power steering control module (J500) using the SVM action code as listed in the table below if necessary.

Model	Engine and/or Transmission (if applicable)	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Action Code
A4/S4	All variants	*	0505	*	0506	48K4A001
A5/ S5/ Cabriolet	All variants	*	0505	*	0506	48K4A001
A6	All variants	×	0008 or below	*	0009	48K4A001
A7	All variants	*	0008 or below	*	0009	48K4A001

© 2012 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Warranty

Update Time Requirements/ Reimbursement	To ensure prompt and proper payment, be sure to immediately enter the applicable reimbursement code listed below upon completion of the repair work. Claims will be paid only for vehicles that show the 48K4 code in the ElsaWeb Campaign/Action Information screen on the day of repair.			
48K4 Saga Claim Entry Pro	ocedure			
Check ElsaWeb to determine	e whether Update 48K4 is open.			
Service No.: 48K4				
Damage Code: 0099				
Parts Manufacturer - Remo	ved part: 002			
Claim Type				
Sold vehicle = 7 10				
Unsold vehicle = 7 90				
Saga Accounting Instruction	ons			
Criteria ID	Repair operation	Labor Operation Number	τυ	
44	No update required	0183 00 99	20 TU	
	Update J500 control module	4840 25 99	40 TU	
There is no reimbursement f	or vehicle wash or loaner vehicle.			
If the vehicle is outside of	the specified warranty period, the	customer has the option to pay fo	r the repair.	
If the customer agrees to pay	y for the repair:			
Fax the information to (248) Number and Date.	754-5093 and provide VIN, applicable	e Service Number, Customer Info, De	ealer	
If the customer does not agr	ee to pay for the repair:			
Fax the information to (248) Number and Date.	754-5093 and provide VIN, applicable	e Service Number, Customer Info, D	ealer	

^{© 2012} Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Additional Actions	Some of the affected vehicles may be involved in additional Actions. Please check your ElsaWeb Campaign/Action Information screen so that any additional required work can be done simultaneously.
Update Verification	For verification, <i>always</i> check the ElsaWeb Campaign/Action Information screen. The ElsaWeb system is the <i>only</i> binding inquiry and verification system; other systems are not valid and <i>may result in non-payment</i> of a claim.
Help for Claim Input	For questions regarding claim input, contact the Warranty Helpline.
Required Customer Notification	Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

Additional Information

All parts and service references provided in this Update are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2012 Audi of America, Inc.

Page 4 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.