



Service Bulletin



SERVICE UPDATE

SUBJECT: Service Update for Inventory and Customer
Erroneous Electric Park Brake Message and Light, DTC C027D
Expires with Base Warranty

MODELS: 2013 Chevrolet Volt

This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

PURPOSE

This bulletin provides a service procedure to reprogram the Electronic Parking Brake Control Module on **certain** 2013 model year Chevrolet Volt vehicles. During vehicle startup, the Electric Park Brake telltale and the Service Electric Parking Brake telltale may illuminate in error.

This service procedure should be completed as soon as possible on involved vehicles currently in dealer inventory and customer vehicles that return to the dealer for any type of service during the New Vehicle Limited Warranty coverage period.

VEHICLES INVOLVED

All involved vehicles are identified by VIN in the Global Warranty Management System – Investigate Vehicle History Application. Dealership technicians should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

Additionally, a list of involved vehicles currently in dealer inventory is available on the “Service Update Bulletin Information” link under the “Service” tab in GM GlobalConnect (US) or attached to the GlobalConnect message (Canada) used to release this bulletin. Customer vehicles that return for service, for any reason, and are still covered under the vehicle's base warranty should also be checked for vehicle eligibility.

PART INFORMATION

No parts are required for this service update.

SERVICE PROCEDURE

Do not attempt to order the calibration number from GM Customer Care and Aftersales. The calibration numbers required for this service procedure are programmed into control modules via a Multiple Diagnostic Interface (MDI) with the calibration update. When using a MDI for reprogramming, ensure that it is updated with the latest software version. Use **TIS2WEB on or after 11/14/12** to obtain the calibration. If you cannot access the calibration, call the Techline Customer Support Center and it will be provided.

For step-by-step programming instructions, please refer to SI and the Techline Information System (TIS) terminal.

1. Verify that there is a battery charge of 12 to 15 volts. The battery must be able to maintain a charge during programming. Only use an approved Midtronics® PSC 550 Battery Maintainer (SPS Programming Support Tool EL-49642) or equivalent to maintain proper battery voltage during programming.
2. Reprogram the electronic parking brake control module. Refer to SI and Service Programming System (SPS) documentation for programming instructions, if required.
 - 2.1 Connect the MDI to the vehicle.
 - 2.2 Select J2534 MDI and Reprogram ECU from the Select Diagnostic Tool and Programming Process screen.
 - 2.3 Select *K83 Park Brake Control Module -- Programming* from the Supported Controllers screen.
 - 2.4 Follow the on-screen instructions.
 - 2.5 At the Programming Complete screen select "Proceed with same VIN".
 - 2.6 Select *K83 Park Brake Control Module -- Setup* from the Supported Controllers screen.
 - 2.7 Follow the on-screen instructions.
3. At the end of module programming and setup, clear all diagnostic trouble codes (DTCs).
4. With a scan tool, perform the Parking Brake Cable Adjuster Enabling procedure. Refer to *Parking Brake Cable Adjuster Enabling* in SI.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below.

Labor Code	Description	Labor Time
V2693	Reprogram Electronic Parking Brake Control Module	0.4

DEALER PROGRAM RESPONSIBILITY

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support
Voluntary Technician
Certification

GM CUSTOMER CARE AND AFTERSALES
DCS2853
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 14, 2012

Subject: 12266 – Service Update Bulletin
Erroneous Electric Park Brake Message and Light, DTC C027D

Models: 2013 Chevrolet Volt

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors is announcing Service Update Bulletin 12266 today. The total number of U.S. vehicles involved is approximately 6,800. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The “Investigate Vehicle History” (IVH) screen will be updated November 16, 2012. A list of involved vehicles in dealer inventory is attached to this message.

Service Update Bulletin (SUB) Information Link

The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES