

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Golf	2010-2013	All	All	All	All
GTI	2010-2012	All	All	All	All

Condition

92 12 03 October 17, 2012 2023248 Supersedes V921003 dated May 11, 2010 to include additional model year applicability.

Rear Washer Nozzle Drips after Use

The water from the rear washer nozzle continues to run out after washer is shut off. (Illustration 1)



Illustration 1

Technical Background

Rear washer hose retains washer solvent after use. Without a check valve the excess water will continue to drain off out of the washer nozzle.

Production Solution

No applicable.

© 2012 Volkswagen Group of America, Inc.

Page 1 of 6



Service

Fit a non-return valve in the hose of the rear window washing system.



Observe the flow direction indicator on the non-return valve. The arrow on the valve must point in the flow direction.

Procedure





Illustration 2

Assemble the non-return valve as shown (illustration 2):

- On the first coupling (4) attach one of the connection hoses (1).
- On that the valve (2) followed by the second connection hose (1).
- Finally the second coupling (4).

Now the valve is ready for installation.



• Remove the trim of the rear hatch according to the repair manual.

• Mark the washer hose directly between the clips (illustration 3).



The length between the two marks should be roughly that of the valve (illustration 3).

Illustration 3

$\ensuremath{\textcircled{\text{c}}}$ 2012 Volkswagen Group of America, Inc.

Page 2 of 6





- Detach the hose from the clips and cut out the marked section.
- Put one end of the valve into the hose (illustration 4).

🚺 тір:

Observe the flow direction indicator on the non-return valve. The arrow on the valve must point in the flow direction.

Illustration 4



Push the shrink-fit hose over the non-return valve (illustration 5).

Illustration 5

Page 3 of 6





- Connect the other side with the washer hose.
- Align the shrink-fit hose equally so that there is the same amount of excess length on two ends of the valve (illustration 6).

Illustration 6



Illustration 7

Make sure that the system is tight by warming up the shrink-fit hose till it completely enfolds the valve and fit it in the clips (illustration 7).

© 2012 Volkswagen Group of America, Inc.

Page 4 of 6



Warranty

Golf2010-2013AllAllAllAllAllAllGTI2010-2012AllAllAllAllAllAllClaim Type:Use applicable Claim Type 1)Use applicable Claim Type 1)SAGA CodingSAGA CodingSAGA CodingSAGA CodingSaga Location (Depends on Service No.)92940050Damage Location (Depends on Service No.)92940050Use applicable when indicated in ElsaWeb (L/R)W W 0 2)Labor Operation 3): Remove and install 2 hatch lid trim panels.70922000 = 40 TUW W 0 2)Labor Operation 3): Repair hose for rear window washing system.92544152 = 20 TUVCausal Part:Select labor operation 92544152Diagnostic Time 4)GFF Time expenditure0150000 = 00 TU max.NOO150000 = 00 TU max.NORead Test0132xxx = 00 TU max.NOClaim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim.1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only2) Code per warranty vendor code policy.3) Labor Time Units (TUs) are subject to change with Elsa updates.	Model(s)	Year(s)	Eng.	Code(s)	Trans. Code(s)		VIN Range Fre	om VIN Range To	
Claim Type: Use applicable Claim Type ¹) SAGA Coding Service Number: Damage Code HST Damage Location (Depends on Service No.) Parts Manufacture (removed part) 9294 0050 Use applicable when indicated in ElsaWeb (L/R) W W O ²) Labor Operation ³): Remove and install 2 hatch lid trim panels. 70922000 = 40 TU W W O ²) Labor Operation ³): Repair hose for rear window washing system. 92544152 = 20 TU Select labor operation 92544152 Causal Part: Select labor operation 92544152 Diagnostic Time ⁴) NO GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO 'Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ² Code per warranty vendor code policy. No	Golf	2010-2013	All		All		All	All	
SAGA Coding Service Number: Damage Code HST Damage Location (Depends on Service No.) Parts Manufacture (removed part) 9294 0050 Use applicable when indicated in ElsaWeb (L/R) W W O ²) Labor Operation ³⁾ : Remove and install 2 hatch lid trim panels. 70922000 = 40 TU W W O ²) Labor Operation ³⁾ : Repair hose for rear window washing system. 92544152 = 20 TU Select labor operation 92544152 Causal Part: Select labor operation 92544152 Diagnostic Time ⁴) GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1' Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ⁹ Code per warranty vendor code policy. Use applicable output for the part output for the p	GTI	2010-2012	All		All		All	All	
Service Number: Damage Code HST Damage Location (Depends on Service No.) Parts Manufacture (removed part) 9294 0050 Use applicable when indicated in ElsaWeb (L/R) W W O ²) Labor Operation ³⁾ : Remove and install 2 hatch lid trim panels. 70922000 = 40 TU W W O ²) Labor Operation ³⁾ : Repair hose for rear window washing system. 92544152 = 20 TU 92544152 Causal Part: Select labor operation 92544152 Diagnostic Time ⁴) GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ² Code per warranty vendor code policy. Parts Manufacture	Claim Type:					Use applicable Claim Type ¹⁾			
Service Number: Damage Code HST Cepends on Service No.) Parts Manufacture (removed part) 9294 0050 Use applicable when indicated in ElsaWeb (L/R) W W O ²) Labor Operation ³⁾ : Remove and install 2 hatch lid trim panels. 70922000 = 40 TU W W O ²) Labor Operation ³⁾ : Repair hose for rear window washing system. 92544152 = 20 TU V Causal Part: Select labor operation 92544152 Diagnostic Time ⁴) GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. NO '' Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only and the section of the secti				SAGA	Coding				
9294 0050 when indicated in ElsaWeb (L/R) W W O ²) Labor Operation ³⁾ : Remove and install 2 hatch lid trim panels. 70922000 = 40 TU TU Labor Operation ³⁾ : Repair hose for rear window washing system. 92544152 = 20 TU 92544152 = 20 TU Causal Part: Select labor operation 92544152 Diagnostic Time ⁴) GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only a) Code per warranty vendor code policy. Warranty in which case this Technical Bulletin is informational only	Service Number:	•	•				epends on	Parts Manufacturer (removed part)	
trim panels. 92544152 = 20 TU Labor Operation ³): Repair hose for rear window washing system. 92544152 = 20 TU Causal Part: Select labor operation 92544152 Diagnostic Time ⁴) GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only 2' Code per warranty vendor code policy. Diagnosi	9294	0050	0050		when		indicated in	W W O ²⁾	
washing system. Select labor operation 92544152 Causal Part: Select labor operation 92544152 Diagnostic Time ⁴⁾ Diagnostic Time ⁴⁾ GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ²⁾ Code per warranty vendor code policy. NO	•	^{):} Remove and ins	stall 2 h	atch lid	70922000	= 40 TL	J		
Diagnostic Time ⁴⁾ GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only 2) Code per warranty vendor code policy. 10	•	⁹⁾ : Repair hose for	rear w	indow	92544152	= 20 TL	J		
GFF Time expenditure 01500000 = 00 TU max. NO Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only 2) Code per warranty vendor code policy.	Causal Part:				Select labor operation 92544152				
Road Test 01210002 & 01210004 NO Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. 1) ***/*********************************				Diagnost	tic Time ⁴⁾				
Technical Diagnosis 0132xxxx = 00 TU max. NO Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. ¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ²⁾ Code per warranty vendor code policy.	GFF Time expenditure 01500000 = 00 T			000 = 00 TL	J max.			NO	
Claim Comment: Input "As per Technical Bulletin 2023248" in comment section of Warranty Claim. ¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ²⁾ Code per warranty vendor code policy.	Road Test 0121		01210	1210002 & 01210004		NO			
¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ²⁾ Code per warranty vendor code policy.	Technical Diagnosis 0132		0132x)132xxxx = 00 TU max.			NO		
²⁾ Code per warranty vendor code policy.	Claim Comment:	Input "As per Tec	hnical	Bulletin 20	23248" in c	ommer	nt section of W	arranty Claim.	
	¹⁾ Vehicle may be	outside any Warr	anty in	which case	e this Tech	nical B	ulletin is inforr	national only	
³⁾ Labor Time Units (TUs) are subject to change with Elsa updates.	•	, ,							
⁴⁾ Documentation required per Warranty Policy & Procedures Manual.				-	-				



Required Parts and Tools

Part Description	Part No:	Quantity	
Hose	443955665	2	
Valve	113955975C	1	
Shrink-Fit Hose	000979992A	1	
Coupling	1J0955875R	2	

No Special Tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2012 Volkswagen Group of America, Inc.