



Service Bulletin

File in Section: -

Bulletin No.: PIC5136L

Date: October, 2012

PRELIMINARY INFORMATION

Subject: Clicking Noise From Front Wheels

Models: 2009 - 2013 Cadillac CTS-V Models
Built Prior to VIN Breakpoint D0106083

This PI was superseded to update recommended field. Please discard PIC5136K.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment on a clicking noise emanating from the front wheels. This condition is noticed at low speed (walking speed) during full wheel lock turns on dry clean pavement (Full lock parking lot maneuver). The clicking noise is generally noted as approximately 1 to 4 "clicks" per wheel revolution.

The CTS-V has lightweight high performance front rotors with an aluminum center. The clicking sound is caused by interaction between the wheel mounting face and wheel mounting surface on the brake rotor caused by the aluminum-to-aluminum interface.

Recommendation/Instructions

Note: Do NOT replace the front wheel or brake rotor for the clicking condition. The new brake rotors that were previously advised to be installed for this condition should no longer be installed. The recommended procedure is to now clean all wheels and rotor top hats as well as replace all wheel nuts as described below.

Procedure:

1. Remove front wheels
2. Clean wheels as follows:
 - a) Use a clean cloth dampened with GM Brake Parts Cleaner (P/N 19287400 or equivalent).
 - b) Wipe the mounting surface of the wheel to remove any residual grey or black material that has accumulated on the wheel mounting surface. Be careful not to use the Brake Cleaner on the painted or clear coated surfaces of the wheel. It is also helpful to use a Scotch-Brite Cleaning Pad to aid in cleaning.

Note: Be sure NOT to use the scotch pads (Roloc disc) on the aluminum material. All cleaning MUST be done by hand. Do NOT use ANY air or power tools!

3. Clean the rotor top hat as follows:
 - a) Use clean cloth dampened with GM Brake Parts Cleaner (P/N 19287400 or equivalent).
 - b) Clean the wheel mounting surface of the rotor (rotor top hat) to remove any residual grey or black material that has accumulated on the rotor. During the cleaning process be sure to clean the rotor near the wheel pilot at the center of the rotor. It is also helpful to use a Scotch-Brite Cleaning Pad to aid in cleaning.

Note: Be sure to NOT use scotch pads (Roloc discs) on the aluminum material. All cleaning MUST be done by hand, do NOT use ANY air or power tools!

Note: Be sure to thoroughly dry the wheel and rotor prior to installation on vehicle.

4. Reinstall wheels using replacement wheel nuts with P/N 9598179 (quantity 20 required for all 4 wheels) (these can be identified with a blue color on the inboard conical portion of the nut (see pic) and torque them to 190 Nm.



2905436

Note: If a car had the 2-piece rotors installed (P/N 20795300 & 20795302) prior to the release of these "blue cone" wheel nuts and has a repeat wheel click concern, perform this cleaning procedure, replace the wheel nuts with the new blue cone nuts, and torque to 190 Nm.

Note: If the vehicle owner has installed a locking lug nut kit, a "blue cone" replacement locking kit (P/N 19259109) must be installed in place of owner's added kit.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
H9752	Clean Mating Surface Of Wheel and Rotor to Correct Noise Concern (both sides)	0.6 hr

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.