

Service Bulletin

File in Section:

Bulletin No.: PI0658

Date: January, 2012

PRELIMINARY INFORMATION

Subject: Fuel Gauge Reading Low, Slow/Delayed Response After Fuel Fill

Models: 2012 Buick LaCrosse, Regal

2012 Cadillac Escalade (Non-Hybrid), Escalade ESV, Escalade EXT, SRX

2012 Chevrolet Avalanche, Impala, Silverado 2500/3500, Suburban 1500, Tahoe

(Non-Hybrid)

2012 GMC Sierra 2500/3500, Yukon (Non-Hybrid), Yukon XL 1500

Equipped with Gasoline Engines Only Vehicles Built Prior to January 1, 2012

Condition/Concern

Some customers may comment that the fuel gauge displays less fuel than the actual amount in the tank, and/or that the gauge is slow to display the correct fuel level after fill.


During diagnosis it may be observed that after fueling the vehicle with the ignition OFF, and then starting the engine, the fuel gauge will display less than the correct level, or is slow to display the correct level.

This condition may be caused by a misshaped fuel level sensor housing that is hindering the sweep motion of the float arm.


Recommendation/Instructions

Warning: Gasoline or gasoline vapors are highly flammable. A fire could occur if an ignition source is present. Never drain or store gasoline or diesel fuel in an open container, due to the possibility of fire or explosion. Have a dry chemical (Class B) fire extinguisher nearby.


- 1. If after following the published Service Information Diagnostics, it is determined that the fuel level sensor is suspect, then remove the fuel level sensor for an inspection. Refer to Fuel Level Sensor Replacement in SI.
- 2. Remove the fuel level sensor from the fuel tank fuel pump module.
- 3. Inspect the fuel level sensor for the following conditions:
 - 3.1. Completely sweep the fuel level sensor float arm several times while feeling for any hindrance of motion in the travel of the float arm.



3.2. Completely sweep the fuel level sensor float arm several times while listening for any noise originating from the area indicated.



2753180



2753203

- 3.3. Inspect visually and by using your finger, the fuel level sensor housing for a misshapen or distorted condition, such as a depression, which is shown in the area indicated.
- \Rightarrow If the fuel level sensor exhibits any of the above conditions, replace the fuel level sensor.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
L1197	Fuel Level Sensor Replacement	Use Published Labor Operation Time