



Service Bulletin

File in Section: -

Bulletin No.: PIC5760

Date: October, 2012

PRELIMINARY INFORMATION

Subject: Various Exterior Lighting Inoperative After BCM Reprogramming

Models: 2012 - 2013 Chevrolet Corvette
Equipped with 7.0L Engine (RPO LS7)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Immediately after the BCM has been reprogrammed, the turn signals, backup lamps, and high beam headlamps may have become inoperative. The vehicle may also exhibit a discharged battery. These concerns will be noticed immediately after the BCM was reprogrammed using a Tech 2. This may occur after the BCM was either replaced and reprogrammed, or if the existing module in the vehicle was only reprogrammed. This concern is caused by a software / setup issue between the BCM and the Tech 2.

Recommendation/Instructions

If the concern is encountered, do not replace any components on the vehicle. Contact Techline Customer Support Center (TCSC: 800-828-6860) for programming assistance in order to resolve this concern.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.