Technical Journal

TITLE: Clunking/pulling, Bushing in rear stay broken **REF NO: ISSUING DEPARTMENT: CAR MARKET:** TJ 25336 **Technical Service United States** PARTNER: **ISSUE DATE:** 3 US 7510 Volvo Cars North America MONTH YEAR DAY 11 28 2012 FUNC DESC: FUNC GROUP: Page 1 of 17 6522 **Cross stay**

"Fixed Right — First Time"

Attachment

File Name	File Size
TJ Instruction-370831-2_1_1_en-US[1].pdf	0.9830 MB
TJ 25336 -1.jpg	0.0547 MB
ТЈ 25336 -3.jpg	0.2355 MB
ТЈ 25336 -4.jpg	0.0809 MB
TJ 25336 -5.jpg	0.0663 MB
ТЈ 25336 -2.jpg	0.4504 MB

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2007-9999		0000001-99999999	200606-999999
134							2011-9999		0000001-99999999	201020-999999
135							2008-9999		0000001-99999999	200720-999999
136							2008-9999		0000001-99999999	200720-999999
156							2009-9999		0000001-9999999	200835-999999

CSC Customer Symptom Codes

Code	Description		
QF	Steering/Constant pull to left		
QG	Steering/Constant pull to right		
QH	Steering/Other steering/handling problems		
E7	Suspension/Unusual noise		
WZ	Suspension/Clicking/clonking noise		

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2012 VOLVO CARS OF NORTH AMERICA, LLC



DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

The front bushing in the rear longitudinal stay may fail, causing one or more symptoms:

- Knocking / clunking noise from rear suspension on uneven roads.
- Pulling / drifting due to incorrect wheel alignment / rear wheel camber angle.
- Unstable rear suspension on curvy roads.

The analysis indicates that there could be some corrosion on the bushing's outer metal ring, which causes the vulcanized rubber to loosen.

PRODUCT MODIFICATION:

Waxed bushings, which may reduce corrosion, were introduced in production from 2012w10. Approx. chassis breakpoints:

124-161000 135-242000 136-140000 134-134000 156-324000

SERVICE:

Replace the bushing according to the attached TJ Instruction.

After installing the new bushing, spray rust proofing wax on the bushing outer metal ring to prevent repeat repair (picture #3).

Parts:

Note: Parts will be listed in Parts Catalogue from VIDA 2012DU2.

Bushing, left side with standard attachment (see picture #4): PN 31387280 Bushing, left side with large attachment (see picture #5): PN 31387282 Bushing, right side: PN 31387281

Rust proofing wax: PN 9510226 (500ml/18fl.oz). Use 25ml/0.85fl.oz on each side (50ml/1.8fl.oz total).

Note: Never use other rust preventers! Solvent based chemicals will damage the rubber bushing!

MATERIAL RETURN:

None.



VEHICLE REPORT:

Only required for vehicles produced after the chassis breakpoints listed above. Create a Technical Helpdesk Vehicle Report using Function Group 6522.

VSTG OPERATION NUMBER:

65271-2 Rear longitudinal stay 1 side replace	See VSTG
65272-2 Rear longitudinal stay 2 sides replace	See VSTG
99400-2 General check/adjust acc to Technical Journal	0.1 hours

To view TJ attachments continue to next page: This TJ has six attachments.

VOLVO	Volvo Car Customer Service	TJ Instruction VC	C-370831-2
Title	Bushing front lateral link	Page	1(9)
Action	Replacement	Operation number:	65214-2
			65215-2

Issue	Date	Reason
1	2012-08	First issue

Affected vehicles

Year	Model
2011, 2012,	S60 (11-)
2013	
2007, 2008,	S80 (07-)
2009, 2010,	
2011, 2012,	
2013	
2008, 2009,	S80L
2010, 2011,	
2012, 2013	
2011, 2012,	V60
2013	
2008, 2009,	V70 (08-)
2010, 2011,	
2012, 2013	
2009, 2010,	XC60
2011, 2012,	
2013	
2008, 2009,	XC70 (08-)
2010, 2011,	
2012, 2013	


Special tools			
Description	Part No.		
Ring	999 7469		
Drift	999 7467		
Hydraulic hole cylinder	951 2923		
ОК	999 7468		


Equipment				
Designation	Part No.			
Hydraulic press				

Removal

Note! Removal steps in this procedure may contain installation details.

Follow instructions for lifting points body frame, refer to: Specifications, mechanical 8 - Body and interior 81 - Body frame 810 - general






- Remove the following components:
- ^{1.} Torque:
 - Tie rod to subframe, 110 Nm
- ^{2.} Torque:

Tie rod to longitudinal stay, 110 Nm

^{3.} Torque:

M6, 10 Nm


Vehicles with load-leveling shock absorbers




Torque:


Rear shock absorber to wheel knuckle (Nivomat), 280 Nm


Vehicles without load-leveling shock absorbers




TJ Instruction VCC-370831-2




















Installation




TJ Instruction VCC-370831-2







Page 8 (9)

TJ Instruction VCC-370831-2



To install, reverse the removal procedure.





4.10



