



This Service Information bulletin supersedes SI B61 04 05 **dated July 2005**.

NEW designates changes to this revision

SUBJECT

Power Mirrors and/or Windows are Inoperative

MODEL

NEW E90

NEW Equipped with option 522 (Xenon lights)

SITUATION

The power windows and/or power mirrors are inoperative. The LED on the headlight switch is flashing. There is a check control message for Windows / Mirrors / Headlights. There may also be a complaint of water in one or both headlights. One of the following fault codes may be stored:

- 9CBD - Communication with stepper motor box left defective
- 9CBE - Communication with stepper motor box right defective
- 9CC1 - Communication with mirror driver side defective
- **NEW** 9CC2 - Communication with mirror passenger side defective / Right Stepper Motor Controller (SMC) signaling fault
- 9CCF - Communication with LIN control defective

Left and/or right headlight housing cover is not properly fitted allowing water ingress into the Stepper Motor Controller (SMC) connector.


CAUSE

Left and/or right headlight housing cover is not properly fitted allowing water ingress into the Stepper Motor Controller (SMC) connector.

PROCEDURE


1. **NEW** Perform a vehicle test using ISTA to verify that the faults listed above are stored in the Footwell Module (FRM).

Note: When the ISTA system message displays: Battery voltage only "XX.XX" V. Please connect charger. Please note the



displayed battery voltage reading in the repair order comments section.

2. **NEW** Inspect the connector at each headlight (X13420 – Left and X13421 – Right) assembly for corrosion and replace as necessary.



3. **NEW** Make sure the headlight access covers (1) are installed correctly.
4. **NEW** Clear the faults and test the headlights for proper function.

NEW PARTS INFORMATION

Part Number	Description	Quantity
61 13 6 931 864	12 POL. Socket housing	As needed

NEW WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

Defect Code:	63 12 20 79 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults)
and if necessary, also		
61 25 528	Refer to KSD2	Charging battery
and		

63 99 000

Work time

Work time to inspect and repair
connector(s) as necessary

Labor operation code 00 00 006 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the "Search" button, and then enter the applicable flat rate labor operation in the FR code field.

Even though work time labor operation code 63 99 000 ends in "000," it is not considered a Main labor operation.

Work time (WT) labor operation 63 99 000 requires an individual punch time.

[Copyright © 2012 BMW of North America, LLC]