



# Technical Bulletin

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Passat	2012-2013	2.5L	All	A3_CC040904	A3_CD999999
Beetle	2012-2013	2.5L-2.0T	All	AT_CM621164	AT_DM999999
Jetta	2012-2013	2.5L-2.0T	All	AJ_CM362729	AJ_CD999999

## Condition

01 12 32 November 30, 2012 2031341

**DTC P0441 Stored in the Engine Control Module**

DTC	Description
P0441	EVAP Emission Control System Incorrect Purge Flow

## Technical Background

Production tolerance in Diagnostic Module Tank Leakage (DMTL) pump could cause a false flow reading.

## Production Solution

Updated DMTL pumps as of pumps' production date September 2012. (Pumps marked with a dot (color may vary blue, green, white and yellow), implementation dates from plants unavailable at this time).



**Note:**

**Dot color may vary blue, green, white and yellow.**

# Technical Bulletin



## Service



**Note:**


**A completed DMTL function test is required for reimbursement.**

### Perform the following steps to test the DMTL system.

- Start Engine.
- Connect VAS-Tester to vehicle.




- Start "Vehicle Self-Diagnosis".




- Open "On Board Diagnostic (OBD)".

# Technical Bulletin




- Start Diagnostic session with “01 Engine Electronics”.




- Select “011 Measurement Values”.

# Technical Bulletin




- Select “MVB 30”.




- Make sure the second “0” from the right in row one changes to “1”.

# Technical Bulletin




- If the bit changed to “1” or is already “1” exit MVB.




- Enter “006 Basic Settings”.

# Technical Bulletin




- Select "Basic Settings 70".



- Select "Activate".

# Technical Bulletin



- Check maximum value in row one (lower window).



Tip

No engine restarts necessary!

If maximum value is less than 70%, DMTL is OK, replace the Purge Valve.

If maximum value is greater than 70%, DMTL is not OK and needs to be replaced.

If maximum value is close to 70%, rerun the test 2 more times to get a more accurate reading.



Note:

If percentage value is in question, please contact the Volkswagen Technician Helpline for further instructions.



Note:

**When replacing the DMTL, ONLY replace the pump and not the whole assembly. Claims with DMTL assemblies will be subject to warranty review and potential debit.**

# Technical Bulletin



## Warranty

### Purge Valve Replacement

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Passat	2012-2013	2.5L	All	A3_CC040904	A3_CD999999
Beetle	2012-2013	2.5L-2.0T	All	AT_CM621164	AT_DM999999
Jetta	2012-2013	2.5L-2.0T	All	AJ_CM362729	AJ_CD999999
SAGA Coding					
Claim Type:		Use applicable Claim Type <sup>1)</sup>			
Service Number:	Damage Code	HST	Damage Location (Depends on Service No.)		
2024	0010	--	Use applicable when indicated in ElsaWeb (L/R)		
Parts Manufacturer	Passat, Beetle, Jetta 2.0T		CFW <sup>2)</sup>		
	Passat, Beetle, Jetta 2.5L		BOG <sup>2)</sup>		
Passat 2.5L					
Labor Operation <sup>3)</sup> : Remove and Install Engine Cover			24251917 = 30 TU		
Labor Operation <sup>3)</sup> : Remove and Install Purge Valve:			20241967 = 10 TU		
Beetle 2.5L					
Labor Operation <sup>3)</sup> : Remove and Install Engine Cover			24471917 = 160 TU		
Labor Operation <sup>3)</sup> : Remove and Install Purge Valve:			20241967 = 10 TU		

# Technical Bulletin



Beetle 2.0T		
Labor Operation <sup>3)</sup> : Remove and Install Engine Cover	24471918 = 250 TU	
Labor Operation <sup>3)</sup> : Remove and Install Purge Valve:	20241968 = 10 TU	
Jetta 2.5L		
Labor Operation <sup>3)</sup> : Remove and Install Engine Cover	24251917 = 30 TU	
Labor Operation <sup>3)</sup> : Remove and Install Purge Valve:	20241967 = 10 TU	
Jetta 2.0T		
Labor Operation <sup>3)</sup> : Remove and Install Purge Valve:	20241900 = 30 TU	
Causal Part: Purge Valve -N80-		06J 133 781* 2.0T 06E 906 517 * 2.5L
Diagnostic Time <sup>4)</sup>		
GFF Time expenditure	01500000 = 20 TU max.	YES
Road Test	01210002, 01210004	NO
Technical Diagnosis	01320000 = 10 TU max.	YES
<b>Claim Comment: Input "As per Technical Bulletin 2031341" in comment section of Warranty Claim.</b>		
<p><sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p style="padding-left: 40px;"><sup>2)</sup> Code per warranty vendor code policy.</p> <p style="padding-left: 40px;"><sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p style="padding-left: 40px;"><sup>4)</sup> Documentation required per Warranty Policy Procedures Manual.</p>		

# Technical Bulletin



## Leak Detection Pump (DMTL) Replacement



**Note:**

**When replacing the DMTL, ONLY replace the pump and not the whole assembly. Claims with DMTL assemblies will be subject to warranty review and potential debit.**

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Passat	2012-2013	2.5L	All	A3_CC040904	A3_CD999999
Beetle	2012-2013	2.5L-2.0T	All	AT_CM621164	AT_DM999999
Jetta	2012-2013	2.5L-2.0T	All	AJ_CM362729	AJ_CD999999
SAGA Coding					
Claim Type:		Use applicable Claim Type <sup>1)</sup>			
Service Number:		Damage Code	HST	Damage Location (Depends on Service No.)	
2048		0010	--	Use applicable when indicated in ElsaWeb (L/R)	
Parts Manufacturer		Passat, Jetta, Beetle			BVD <sup>2)</sup>
Passat 2.5L					
Labor Operation <sup>3)</sup> : Remove and Install Wheel			44051900 = 20 TU		
Labor Operation <sup>3)</sup> : Remove and Install Wheel Liner			66761950 = 20 TU		
Labor Operation <sup>3)</sup> : Remove and Install Leak Detection Pump			20481950 = 10 TU		
Beetle 2.5L/2.0T					
Labor Operation <sup>3)</sup> : Remove and Install Leak Detection Pump			20481900 = 90 TU		
Jetta 2.5L/2.0T					
Labor Operation <sup>3)</sup> : Remove and Install Wheel			44051900 = 20 TU		
Labor Operation <sup>3)</sup> : Remove and Install Wheel Liner			66761950 = 20 TU		

# Technical Bulletin



Labor Operation <sup>3)</sup> : Remove and Install Leak Detection Pump		20481950 = 20 TU
Causal Part: Diagnostic Module Tank Leakage (DMTL) pump		7L0 906 243 *
Diagnostic Time <sup>4)</sup>		
GFF Time expenditure	01500000 = 20 TU max.	YES
Road Test	01210002, 01210004	NO
Technical Diagnosis	01320000 = 10 TU	YES
Claim Comment: Input "As per Technical Bulletin 2031341" in comment section of Warranty Claim.		
<p><sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p><sup>2)</sup> Code per warranty vendor code policy.</p> <p><sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p><sup>4)</sup> Documentation required per Warranty Policy Procedures Manual.</p>		

## Required Parts and Tools

Part Description	Part No:	Quantity
DMTL	7L0 906 243*	1
N80	06J 133 781* 2.0T 06E 906 517* 2.5L	1

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940)
VAS Diagnostic Tool	VAS-PC, 5051B, 5052A, 6150X (Base CD V19.01.00 and Brand DVD V19.18.00 or higher)

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.