

# Technical Service Bulletin

#### 02 Transmission warning message in cluster (DTC P0603 in TCM)

02 12 02 2032094/1 December 6, 2012.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4			
A5 Cabriolet	2012-2013	All	CVT Transmission
A6			

## Condition

Customer may report transmission warning light comes on. No drivability/starting concerns. GFF scan shows fault code- **P060300** (Control Module Malfunctioning, Sporadic), stored in the Transmission control module (02).

### **Technical Background**

The entry is caused by a too sensitive diagnosis in the gearbox control unit.

This does not affect the driving characteristics.

# **Production Solution**

Not applicable.

### Service

No repair is available at this time.

- 1. Do not perform any repairs. Any repairs for this concern will be denied.
- 2. Instruct the customer that this condition is known, and a solution is under development.

For payment processing Guided fault Finding Logs must be documented identifying that the applicable fault codes were present and have been cleared. All claims are subject for review.

© 2012 Audi of America, Inc.

#### Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# Technical Service Bulletin

# Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	3730				
Damage Code:	0039				
Diagnostic Time:	GFF Check faults, verify codes listed are present and clear faults.	0150 0000	Time stated on diagnostic protocol (Max 40 TU)		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2032094/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

# **Additional Information**

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2012 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prin expressed written permission of the publisher.