

Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2009-2013	2.0L (CCTA, CBFA)	All	All	All

Condition

24 12 09 December 20, 2012 2032174

Verifying Fuel Injector Replacement

Misfires can be caused by one or multiple injectors.

If an injector is replaced for a misfire concern, the failed injector must have a misfire code (P0301 - P0304) related to the misfiring cylinder.



Note:

Multiple injector replacement SHOULD NOT be replaced for 1 misfiring cylinder.

Technical Background

All injector(s) must accompany a corresponding misfiring cylinder to avoid unnecessary part replacement.

Misfire code P0300 – random/multiple cylinder misfire is not probable cause to replace all fuel injectors. The misfiring cylinder will always accompany a P0300 fault.

Production Solution

N/A

Service

If it is determined through guided fault finding that a fuel injector has caused a misfire, the repair should only include the fuel injector(s) causing the misfire.



Note:

A corresponding misfire fault code for each injector replaced is required for reimbursement.

Multiple injector replacement should be submitted as one claim.

Misfire code P0300 - random/multiple cylinder misfire must have the effected cylinder identified for reimbursement.



Technical Bulletin

Warranty

Information only.

Required Parts and Tools

No special parts required.

No special tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.