

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
(A5) Rabbit, GTI	2006-2007	All	All	All	All
(A5) Jetta	2005-2007	All	All	All	All

Condition

01 12 30 October 3, 2012 **2012705** Supersedes T. B. V010615 dated September 19, 2006 to update warranty information.

Engine, Cranks Intermittently or No Crank

Customer may state that engine cranks intermittently or will not crank. May be more evident when HOT.

Technical Background

May be caused internally when the Steering Column Electronic Systems Control Module -J527- fails, this causes Terminal 50 to not energize high, which results in a no crank condition.

Steering Column Electronic Systems Control Module -J527- performs two operations when starting the vehicle. When ignition is turned to crank position:

- A message is sent via CAN bus to Vehicle Electrical System Control Module -J519-.
- The Terminal 50 circuit between Vehicle Electrical System Control Module -J519- and Steering Column Electronic Systems Control Module -J527- is energized to high.

🚺 Tip:

Fault code for "00885 Ignition/Starter Switch -D- (terminal 50) 008 implausible signal 001 sporadic" may be stored in Vehicle Electrical System Control Module -J519-.

Production Solution

No production change required.

Service

- Verify the output of the Steering Column Electronic Systems Control Module -J527- using VAS 5051/5052.
- Enter address word 16 Steering Wheel Electronics.
- Read Measuring Value Block 3.

In field one, there will be a bit pattern which is relevant to ignition switch status.

Page 1 of 6

^{© 2012} Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.





Similar screen appears:

• Turn ignition switch to the crank position and observe that the last bit cycles from "0" to "1", as shown.


i Tip:

Example of switch in crank position: 01011

If the bit does not cycle, then verify the integrity of the ignition switch (further diagnostics are needed. **DO NOT** continue with this Technical Bulletin).

- Exit address word 16 Steering Wheel Electronics.
- Enter address word 09 Electronic Central Electrics.
- Read Measuring Value Block 7.
- Turn ignition switch to the crank position again and hold.

The first field is a status indication of the Terminal 50 input on pin G1 on the Vehicle Electrical System Control Module -J519-.




Similar screen appears:


If this does not cycle from "**OFF**" to "**ON**", as shown, when in the crank position then the Vehicle Electrical System Control Module -J519is not receiving a Terminal 50 input from the Steering Column Electronic Systems Control Module -J527-.

Verify Terminal 50 circuit and connector terminals between Vehicle Electrical System Control Module -J519- and Steering Column Electronic Systems Control Module -J527-.


Circuit path: Pin 1 on the 12 pin G connector of Vehicle Electrical System Control Module -J519- to pin 18 on the 20 pin connector of the Steering Column Electronic Systems Control Module -J527-.







Steering Column Electronic Systems Control Module -J527- located under steering column, -arrow-.



Connector G located on top of Vehicle Electrical System Control Module -J519-, -arrow-.

If Terminal 50 circuit is valid:

• Replace Steering Column Electronic Systems Control Module -J527-. See Repair Manual Group 94 - Lights, Switches - exterior, Steering Column Switches.

 $\ensuremath{\textcircled{\text{c}}}$ 2012 Volkswagen Group of America, Inc.

Page 3 of 6



i Tip:

It is helpful to copy the coding of the Steering Column Electronic Systems Control Module -J527- prior to exchanging the part.

If Terminal 50 circuit or connector terminals are damaged:

• Repair as necessary.

Warranty

Model(s)	Year(s)	ar(s) Eng. Co		Trans. Code(s)	VIN R Fro	-	VIN Range To
(A5) Rabbit, GTI	2006-2007	6-2007 All		All	A	.11	All
		SAG	A Cod	ing			
Claim Type:	Use applicable Cla	aim Type ¹)				
Service Number:	Damage Code			HST	Damage Location (Depends on Service No.)		
9449	0040				Use applicable when indicated in ElsaWeb (L/R)		
Parts Manufacturer	Parts Manufacturer Rabbit,				See Removed Part ²⁾		
Labor Operation ³⁾ : Steering Column Electronics Module Remove and Install			94491	950 = 10 TU			
Labor Operation ³⁾ : Steering Column Trim Remove and Install			70111950 = 10 TU				
Labor Operation ³⁾ : Steering Wheel Remove and Reinstall			48101950 = 10 TU				
Labor Operation ³⁾ : Driver Airbag Remove and Reinstall			69581900 = 30 TU				
Causal Part:			Steering Column Systems Control Module				
		Diagno	ostic Ti	ime ⁴⁾			
GFF Time expenditure 01500000 = 20 TU			max				YES

© 2012 Volkswagen Group of America, Inc.



Road Test	NO				
Technical Diagnosis0132xxxx = 00 TU max.NO					
Claim Comment: Input "As per Technical Bulletin 2012705" in comment section of Warranty Claim.					
¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only					
²⁾ Code per warranty vendor code policy.					
³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.					
⁴⁾ Documentation required per Warranty Policy Procedures Manual.					

To determine if this procedure is covered under Warranty, always re Procedures Manual ¹⁾	fer to the Warranty P	Policies and

Model(s)	Yea	ar(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To	
(A5) Jetta	2005-2007		All	All	All	All	
			SAGA C	oding			
Claim Type: Use applicable Claim Typ			icable Claim Type) 1)			
Service Number:		Damage Code	HST	Damage Location (Depends o Service No.)			
9449		0040		Use applicable when indicate ElsaWeb (L/R)			
			Jetta		See Rer	noved Part ²⁾	
Labor Operation Module Remove			Electronics	94491950 = 20 T	U		
Labor Operation ³⁾ : Steering Wheel Remove and Reinstall			48101950 = 10 TU				
Labor Operation ³⁾ : Driver Airbag Remove and Reinstall			move and	69581900 = 30 TU			
Causal Part:			Steering Column Systems Control Module				
			Diagnosti	c Time ⁴⁾			
GFF Time expenditure 01500000 = 20			01500000 = 20 T	'U max		YES	
Road Test 012			01210002 01210	01210002 01210004		NO	

© 2012 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Page 5 of 6



Technical Diagnosis	0132xxxx = 00 TU max.	NO			
Claim Comment: Input "As per Technical Bulletin 2012705" in comment section of Warranty Claim.					
¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only					
²⁾ Code per warranty vendor code policy.					
³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.					
⁴⁾ Documentation required per Warranty Policy Procedures Manual.					

Required Parts and Tools

Description	Part No:	Quantity	
Steering Column Electronic Systems Control Module -J527-	Ordered by VIN	1	

Tool Description	Tool No:	
Midtronics Battery Tester/Charger	InCharge 940 (INC-940)	
VAS Diagnostic Tool	VAS-PC, 5051B, 5052A, 6150X	
	(Base CD V19.01.00 and Brand DVD V19.18.00 or higher)	

© 2012 Volkswagen Group of America, Inc.

Page 6 of 6