ATTENTION:

GENERAL MANAGER

PARTS MANAGER

•

IMPORTANT - All

Service Personnel

Should Read and

SERVICE PROCEDURE / INFORMATION



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD **RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Continued... SUBARU OF AMERICA, INC. IS

"ISO 14001 COMPLIANT'

The international standard for excellence

in Environmental Management Systems.

Please recycle or dispose of automotive

products in a manner that is friendly to our

environment and in accordance with all

local, state and federal laws and regulations.

outlined in steps 2 and 3 below **MUST** be completed and your results recorded.

and #15 (ground). Specified value is 4.8v to 5.2v. If the voltages are outside of the specified range, the TCM is damaged along with the pulley surfaces of the CVT due to chain slippage. Replace both the TCM and the CVT assembly. **IMPORTANT:** Although both the TCM and CVT assembly may need to be replaced, the testing

1. With the ignition switch on and engine off, check the voltage between pin #2 (power supply)

voltage checks. Perform the following voltage checks on the TCM connector, B54:

SSMIII and gaining access to the Transmission Control Module (TCM) main wiring harness connector. This will allow the secondary pressure sensor sufficient time to fully drain off any residual fluid pressure.

After connecting the SSMIII, confirm the CVT's fluid temperature is between 10° and 80°C

(50°- 176°F). NOTE: DO NOT start the engine at any time while performing the following

- temperature.
- Turn off the ignition and allow the vehicle to sit at least 10 minutes while preparing the •
- Road test the vehicle to confirm the condition and bring the transmission up to normal operating •
- **INTRODUCTION** This Bulletin provides an inspection and diagnosis method for the CVT's secondary pressure sensor

which if failed, could create a customer concern of a squealing-type sound during light throttle application. The Service Manual will be revised in the future with this information.

SUBJECT: CVT Secondary Pressure Sensor Diagnostics

🐼 SUBARU

REVISED: 12/12/12

CLAIMS PERSONNEL	Initial in the boxes provided, right.		UALITY DRIVEN	[®] SERVICE
	SERVI	CE BULLETIN		
APPLICABILITY:	2010-2012MY Legacy with CVT	and Outback Models	NUMBER: DATE:	<mark>16-85-12R</mark> 11/26/12

- 2. With the ignition switch on and engine off, check the voltage between pin #17 (pressure sensor output voltage) and #15 (ground). Specified value is 0.45v to 0.55v. If the voltages are outside of the specified range, the secondary pressure sensor is damaged along with the pulley surfaces of the CVT due to chain slippage. Replace the CVT assembly.
- 3. **IMPORTANT:** Before ordering a new TCM and / or CVT, perform these same voltage checks at the secondary pressure sensor connector (AT6) and (if necessary), the main transmission harness connectors (T4 and B11). Ruling out wiring issues will prevent repeat or unnecessary component replacements.



REMINDER: Whenever replacing the CVT assembly, TCM, control valve body or servicing the CVT fluid, the Learning Control procedure must be completed.

WARRANTY / CLAIM INFORMATION

For vehicles within the Basic New Car Limited Warranty period, this repair may be claimed using the following information:

LABOR DESCRIPTION	LABOR OPERATION #	FAIL CODE	LABOR TIME
Remanufactured Transaxle R&R, CVT	B139-301		4.9
TCM R&R	C303-100	TIVIA-25	0.2