

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.

Audi
Truth in Engineering 

Audi Elsa Newsletter

Edition 60: November 4, 2013

Content

- [ODIS Quick Reference Guide](#)
- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



ODIS Quick Reference Guide

Several weeks ago, the ODIS Quick Reference Guide was sent to all dealer technicians (non-corporate users) to assist them in navigating through key ODIS information. For easy access, we are including a link to the document.

Please go to: www.vwHub.com/snetljct/en/web/audi/offboard-diagnostic-information-system-odis to download the ODIS Quick Reference Guide.

Technical Bulletins

69 Replaced airbag control unit cannot be coded (2023323/11)		
Model(s)	Year	Vehicle Specific Equipment
A4, S4, Q5	2009-2015	Not applicable
A5, S5	2008-2015	Not applicable
A5 Cab	2010-2015	Not applicable
TT, TTS, R8 Coupe, Spyder	2007-2015	Not applicable
A3	2009-2014	Not applicable
A6	2009-2011	Not applicable
A8	2011-2015	Not applicable
A6, A7	2011-2012	Not applicable
<p>Condition: After the airbag control module has been replaced, the control unit cannot be coded via SVM spec/actual. Production Solution: Not applicable.</p>		

00 Oil filling procedure for W12 engines (2035581/1)		
Model(s)	Year	Vehicle Specific Equipment
A8	2012-2014	CEJA engine
<p>Condition: Although the correct amount of oil was added to the engine during an oil change service, a check of the oil level shows that the oil level is not okay. Production Solution: Not applicable.</p>		

74 S-line front seat head restraint feed-through hole exposed in leather backrest cover (2018257/5)		
Model(s)	Year	Vehicle Specific Equipment
A6	2006-2009	S-line Sport Seats
<p>Condition: The head restraint feed-through hole is visible on the seat backrest cover. Production Solution: The construction of the S-line seat backrest cover has been optimized in production vehicles. The changes included the following:</p> <ul style="list-style-type: none"> The locations of the feed-through holes were moved back. 		

- The diameter of the feed-through holes was reduced.
- An additional piece of stabilizing material was attached to the inside of the backrest cover around the holes to ensure better adhesion of the leather to the seat back cushion.

72 Rear center seat rattles and does not fold flat (2023324/3)

Model(s)	Year	Vehicle Specific Equipment
Q5	2009-2010	Not Applicable
<p>Condition: The rear center seat rattles at the backrest latching mechanism. The rear center seat release handle for folding the center seat backrest flat does not function.</p> <p>Production Solution: The connection between the release rod and the release lever is optimized. The release lever is optimized.</p>		

74 Seat heating performance too low (2028257/8)

Model(s)	Year	Vehicle Specific Equipment
Q5	2012	Heated front seats
<p>Condition: The customer may complain that the seat heating temperature is too low or that it takes too long to heat up.</p> <p>Production Solution: Change in preparation.</p>		

72 Rattle from left rear seat back (2030729/4)

Model(s)	Year	Vehicle Specific Equipment
Q5	2009-2013	Not Applicable
<p>Condition: Customer may report hearing squeak or rattle sounds coming from the rear seat area.</p> <p>Production Solution: Improved 2/3 rear seatback frame torsion bar to pivot incorporating internal plastic guides. The striker pin has also been improved to reduce the contact surface with the lock.</p>		

87 A/C compressor replacement (2035582/1)

Model(s)	Year	Vehicle Specific Equipment
All	2009-2014	Not Applicable
<p>Condition: The A/C Compressor has been diagnosed as faulty and will be replaced under warranty. Production Solution: Not applicable.</p>		

17 Electronic oil consumption measurement - Repair Authorization 3.0T MY 2013/14 (2035463/1)		
Model(s)	Year	Vehicle Specific Equipment
A4, A5, A5 Cab, A6, A7, A8, Q5, Q7	2013-2014	3.0T engine
<p>Condition: If there is a customer complaint about oil consumption, follow the procedure. Production Solution: Not applicable.</p>		

17 Engine oil consumption - Customer complaints, 3.0T TFSI Model Year 2009-2012 (2030197/11)		
Model(s)	Year	Vehicle Specific Equipment
A4	2010-2012	3.0 TFSI
A6	2009-2012	3.0 TFSI
A7	2012	3.0 TFSI
Q7	2011-2012	3.0 TFSI
<p>Condition: Customer complains of excessive oil consumption. Production Solution: Crankcase pressure reduction starting with model year 2013.</p>		

01 MIL on (DTC P0456 or DTC P0442 (EVAP emission control system

leak detected)) (2035519/1)		
Model(s)	Year	Vehicle Specific Equipment
Q7	2013-2014	Not Applicable
<p>Condition:</p> <ul style="list-style-type: none"> • MIL on. • One of the following DTCs is stored in the engine control module: <ul style="list-style-type: none"> • DTC P0456 (EVAP Emission Contr. Sys. (very small leak) Leak Detected) • DTC P0442 (EVAP Emission Contr. Sys. (small leak) Leak Detected) <ul style="list-style-type: none"> • Drivability is not affected. <p>Production Solution: Not applicable.</p>		

Pending Service Solutions

No new pending service solutions this week.

[Back to top](#)

Campaigns

No new campaigns this week.

[Back to top](#)

Updates

19J1 - UPDATE - 4.0 l Quality Package (NVLW)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
S6, S7, A8, S8	2013-2014	None	None	See Campaign/Action screen in ElsaWeb	See Campaign/Action screen in ElsaWeb
<p>A quality package has been defined for Audi vehicles with 4.0L TFSI engine manufactured within a specific period. This Update is in effect until removed. Vehicle must meet all of the following criteria:</p>					

- Procedure is valid only for vehicles that show the 19J1 code in the ElsaWeb Campaign/Action Information screen on the day of repair.
 - Vehicle must be within the New Vehicle Limited Warranty.
 - Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
 - Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

[Back to top](#)

Suggestions

Please send comments or suggestions to: aoa.workshopinformation@audi.com

[Back to top](#)

© 2013 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.