



Service Bulletin

File in Section: -

Bulletin No.: PIC5811

Date: February, 2013

PRELIMINARY INFORMATION

Subject: Knock Sensor Connectors Available Through Warranty Parts Center

Models: 2013 Cadillac ATS
2013 Chevrolet Malibu
with 2.5L (LCV), 2.0L (LTG)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A technician may comment that while removing a knock sensor connector, the connector was damaged or broken. The connector pigtail kit is not yet available through service parts.

Recommendation/Instructions

Until the kit is available through service parts, a connector kit (containing of connector, terminals, & seals) is available through the Warranty Parts Center.

Refer to the knock sensor connector end view in Service Information for the correct release & crimp tools along with pin/terminal locations.

To obtain a new connector, E-mail or fax the form included in this PI to the GM Warranty Parts Center (WPC). Request the WPC # 709 for the appropriate application and configuration noted below:

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N6652	Connector with Leads Assembly Replacement	Use Published Labor Operation Time

WPC Parts Request Form

To: Warranty Parts Center
"E-Mail" warrantypartscenterusa@gm.com
or WPC Fax #: 248-371-0192

Attn: Jeanette Dunn

Part Being Requested:

(1)WPC #

(2)WPC #

(3)WPC #

(4)WPC #

(5)WPC #

(6)WPC #

Dealer BAC (U.S.) / Dealer Code (Canada):

Dealer Name:

Dealer Address:

Dealer Contact Person:

Dealer Phone Number:

Repair Order Number:

Vehicle VIN:

If you do not receive the part within 2 business days after emailing or faxing your part request to the Warranty Parts Center, please call Customer Assistance at 248-371-9901/9902