VW ElsaWeb Newsletter



Das Auto.

Edition 18: January 7, 2013

Content

- <u>ElsaWeb Feedback</u>
 <u>Attachments</u>
- <u>Feedback Corner</u>
- <u>Technical Bulletins</u>
- <u>Tech Tips</u>
- <u>Campaigns</u>
- <u>Updates</u>
- <u>Repair Manuals</u>
- Wiring Diagrams
- <u>Suggestions</u>



ElsaWeb Feedback Attachments

Feedback Corner

This week's feedback is from James regarding a 2010 Routan Repair Manual. He stated:

"The repair manual states "Remove the nut (1) that secures the underbody refrigerant extension lines (3) and the sealing plate (4) to the rear A/C expansion valve (1)" at the start of removal for the rear HVAC housing, it should state "Remove the nut (2) that secures the underbody refrigerant extension lines (3) and the sealing plate (4) to the rear A/C expansion valve (1).""

The Service Information Team reviewed the feedback and was verified that the technician was

correct and the Repair Manual was updated. James included his full name and email address with the feedback and will receive Audi Winner's Circle Rewards for helping improve the quality of the repair information.

Feedback Status					
New	Completed	To Factory			
16	13	0			

*Please note that this feedback feature is not the place to obtain technical assistance on Volkswagen vehicles, or to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create a Volkswagen Technical Assistance ticket and contact the Volkswagen Technical Helpline at (800)-678-2389.

Back to top Technical Bulletins

15	15-12-03 - Proper Removal of Engine Cover to Avoid Breakage (2032150)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
All	II 2009–2013 2.0L TDI (CBEA, CJAA) All All All				All	
	Pulling on the engine cover in some areas can cause damage.					

15-12-04 - Camshaft Adjustment Valve 1 -N205- Diagnosis (2032173)						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
Jetta Sedan, Jetta SportWagen, Jetta Wagon, Rabbit, Golf, Golf Wagon	2009– 2013	2.5L (CBTA, CBUA)	5 spd Manual (MQ250) 6 spd Automatic (AQ250)	All	All	
Passat, Beetle, Beetle Convertible	2012– 2013	2.5L (CBTA, CBUA)	5 spd Manual (MQ250) 6 spd Automatic (AQ250)	All	All	

Completing the GFF function test and performing basic settings on the camshaft adjustment valve are essential to diagnose proper operation and to avoid unnecessary replacements.

15·13·01 - Camshaft Adjustment Valve 1 -N205- Diagnosis (2032173)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta Sedan, Jetta SportWagen, Jetta Wagon, Rabbit, Golf, Golf Wagon	2009– 2013	2.5L (CBTA, CBUA)	5 spd Manual (MQ250) 6 spd Automatic (AQ250)	All	All
Passat, Beetle, Beetle Convertible	2012– 2013	2.5L (CBTA, CBUA)	5 spd Manual (MQ250) 6 spd Automatic (AQ250)	All	All

Completing the GFF function test and performing basic settings on the camshaft adjustment valve are essential to diagnose proper operation and to avoid unnecessary replacements.

17-12-06 - Possible Oil Leak from Oil Filter Housing (2032198)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta	2011– 2013	2.5L (CBTA, CBUA)	5spd Manual / MQ250 6spd Automatic / AQ250	AJ_BM300230	AJ_DM366492
Jetta SportWagen, Golf Wagon	2011– 2013	2.5L (CBTA, CBUA)	5spd Manual / MQ250 6spd Automatic / AQ250	AJ_BM600203	AJ_DM622987
Golf	2011– 2013	2.5L (CBTA, CBUA)	5spd Manual / MQ250 6spd Automatic / AQ250	AJ_BW000445	AJ_DW999999
Passat	2012– 2013	2.5L (CBTA, CBUA)	5spd Manual / MQ250 6spd Automatic / AQ250	A3_CC000001	A3_DC02522
Beetle, Beetle Convertible	2012– 2013	2.5L (CBTA, CBUA)	5spd Manual / MQ250 6spd Automatic / AQ250	AT_CM601051	AT_DM620428

may prevent a proper seal when installed and result in an oil leak.

17-12-07 - Possible Oil Leak after Oil Filter Change (2029091)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta 2011–2013 2.0L (CBPA) All All All					
Due te the me	Due to the mean time design of the empire oil cooley, it is measible for the oil cooley to be some locate				

Due to the mounting design of the engine oil cooler, it is possible for the oil cooler to become loose during an oil service. If this happens, an oil leak may occur between the oil cooler and the oil filter adaptor housing. This condition can be corrected by tightening the oil cooler mounting nut. DO NOT replace any parts for this condition.

24-12-10 - MIL- ON Sporadic Intake Air Faults (2031855)						
Model(s)	el(s) Year Eng. Code Trans. Code VIN Range From VIN Range To					
All	2012-2013	2012–2013 2.0L (CCTA, CBFA)		All	All	
Completion of the MAF sensor (G70) function test is important to ensure proper diagnosis. Sporadic faults can be caused from loose wiring connections, unsecure terminals, corrosion or damaged						

wires.

	24-12-09 - Verifying Fuel Injector Replacement (2032174)						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To		
All	2009–2013 2.0L (CCTA, CBFA) All All All				All		
replaceme	All injector(s) must accompany a corresponding misfiring cylinder to avoid unnecessary part replacement. Misfire code P0300 – random/multiple cylinder misfire is not probable cause to replace all fuel injectors. The misfiring cylinder will always accompany a P0300 fault.						

28-12-06 - MIL ON, DTC(s) P0671, P0672, P0673 and/or P0674 Stored in ECM Fault Memory (2029514)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, Jetta Sportwagen, Golf Wagon	2011– 2012	2.0L (CJAA)	All	All	All
Jetta	2011– 2012	2.0L (CJAA)	All	All	All
Passat	2012	2.0L (CKRA)	All	All	All
Internal hardware issue of the g	ow plug rela	y may cause c	an over volta	ge supply to the	glow plug(s

damaging the heating element (figures 1 and 2).

30-13-01 - DTC P2711 Implausible Transmission Shift Sequence Stored in the Transmission Control Module (2028714)

			- (
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
A5 Jetta Wagon	2009	All	DSG (02E)	All	All
A5 Golf	2009	All	DSG (02E)	All	All
A5 Jetta Sedan	2009–2010	All	DSG (02E)	All	All
A6 Jetta Sportwagen, Golf Wagon	2010–2012	All	DSG (02E)	All	All
Passat, CC	2009–2012	All	DSG (02E)	All	All
EOS	2009–2012	All	DSG (02E)	All	All
Debris in the clu	tch assembly c	ausing too m	uch drag torqu	e from the multiple	e clutch.

Back to top **Tech Tips**

Currently, the Service Information Team is working to move the Tech Tips to ElsaWeb. The Team has transferred the majority of the 2007–2012 Tech Tips to ElsaWeb and is continuing to work to transfer all Tech Tips over the next few months. The Team thanks you for your patience during this transition.

No new Tech Tips in ElsaWeb. <u>Back to top</u> **Campaigns**

No new Campaigns in ElsaWeb.

Back to top Updates

No new Updates in ElsaWeb. <u>Back to top</u>

Repair Manuals

No new Repair Manuals in ElsaWeb.

Back to top

Wiring Diagrams

Elsa Name	Model	Book Updated
A32	Passat 2012>	2.5L gasoline engine, CBUA, from January 2011
3C	Passat 2006–2010	Parking aid, from May 2008
1K5	Jetta Sportwagen 2009	Climatronic, from May 2007
1F7/1F8	EOS 2007>	Automatic transmission (DSG) 02E, from November 2009
162	Jetta 2011>	Multiple
7P5	Touareg 2011>	Multiple
5C7	Beetle Convertible 2012>	Multiple

Back to top

Suggestions:

Back to top

© 2012 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.