

TECHNICAL BULLETIN
JTB00311NAS1
26 SEP 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 412-03

Climate Control System Odor

AFFECTED VEHICLE RANGE:

XF (X250)

Model Year: 2012 Onwards
VIN: S59096 Onwards

XJ Range (X351)

Model Year: 2012 Onwards
VIN: V39036 Onwards

XK Range (X150)

Model Year: 2012 Onwards
VIN: B49778 Onwards

F-TYPE (X152)

Model Year: 2014 Onwards
VIN: K00222 Onwards

MARKETS:

USA

CONDITION SUMMARY:

Situation: An odor may be present when the Climate Control System is switched 'ON'.

Cause: This may be caused by mold spore accumulation / build-up in the evaporator core.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

| | | |
|----------|------------------------------|-------------|
| C2D22759 | Evaporator core - XF, XJ | Quantity: 1 |
| C2P23642 | Evaporator core - F-TYPE, XK | Quantity: 1 |

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART |
|----------------------------------|----------|--------------|----------------|-------------|
| Evaporator core - Renew - F-TYPE | 82.25.20 | 6.0 | 49 | C2P8713 |

| | | | | |
|----------------------------------|-----------------|------|----|---------|
| Evaporator core - Renew - XF | 82.25.22 | 6.6 | 49 | C2Z6527 |
| Evaporator core - Renew - XJ | 82.25.20 | 10.5 | 49 | C2Z6527 |
| Evaporator core - Renew - XK N/A | 82.25.20 | 4.4 | 49 | C2P8713 |
| Evaporator core - Renew - XK SC | 82.25.20 | 4.5 | 49 | C2P8713 |



NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1.  **NOTE: Prior to installation of new evaporator core, wash out the evaporator core housing with warm water to remove any mold spore accumulation.**

Replace the evaporator core (see TOPIx Workshop Manual, Section 412-03).