Service Bulletin

Bulletin No.: PIP5165

Date: Nov-2013

PRELIMINARY INFORMATION

Subject: Oil Dripping Out Of The Air Filter Box

Models: 2014 Chevrolet Corvette

6.2L LT1 dry sump engine w/manual or auto trans

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

If the customer drives aggressively with low miles on the car it is possible to push oil through the PCV system.

Recommendation/Instructions

No internal repairs are required.

Change the oil and filter.

Remove the air cleaner assembly.

Clean any oil out of the filter housing and duct.

Remove the MAF clean off any oil.

Make sure that there is no residual oil in the PVC lines.

Install a new air filter in the air box.

Reinstall the air box assembly.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4020390	Air Cleaner Assembly Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

