

Bulletin No.: PIC5937

Date: Nov-2013

PRELIMINARY INFORMATION

Subject: Missing Audible Alert For Front Collision Alert system – Updated Calibration

Models: 2014 Buick LaCrosse

with Forward Collision Alert (RPO UEU) and Base Audio (RPO U65)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

On certain 2014 model year Buick LaCrosse vehicles, the beep alert option on the Forward Collision Alert (FCA) System may be inoperable. If the beep alert is selected for the forward collision alert system, the beep will not sound; however, a red flashing alert on the windshield remains active.

Recommendation/Instructions

An updated software calibration has been released to address the above condition. Update the Instrument Panel Cluster (IPC) with the latest calibration using the Service Programming System (SPS) via TIS2WEB. Refer to the SPS procedures in SI.

Warranty Information

For vehicles repaired under warranty use:

Labor Ope	eration	Description	Labor Time
28101	95 Instrume	ent Cluster Reprogramming with SPS	0.3 hr

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION