



Service Bulletin

PRELIMINARY INFORMATION

Subject: LT1 Engines May Have Been Built With An Oil Filter That Has An Incorrect Label

Models: 2014 Chevrolet Corvette
Equipped with engine RPO LT1 6.2L

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some early LT1 engines may have been built with an oil filter that has an incorrect label on the can.

The filter is correct. However, the label is wrong.

Recommendation/Instructions

Replacement of the filter for the incorrect label concern is not necessary.

The technician needs to be sure to replace the OE filter with the correct PF64 when it is time for an oil and filter change.

The incorrect label says to replace the oil filter with a PF63. The correct service part is a PF64 part # 12640445.

Filter with the wrong label



Filter with the right label



Caution: The PF63 will fit the engine. However, it is significantly longer and it is possible it could be damaged if the suspension goes to full compression.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION