



Service Bulletin

PRELIMINARY INFORMATION

Subject: Unwanted Alarm Sounding (GM Accessory Inclination Sensor Mounting)

Models: 2007-2013 Cadillac Escalade Models
2007-2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe
2007-2013 GMC Sierra, Yukon Models

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.


Condition/Concern

Some owners may comment that for no reason the alarm will go active. This would normally occur after the vehicle has been sitting awhile following a drive cycle. The sensor was originally positioned on the driver's side lower HVAC duct. With thermal cycling the duct could expand and contract enough that, depending on exact sensor location, movement of the duct might cause the sensor to trip and activate the alarm.

Recommendation/Instructions

To verify the alarm was activated by the inclination sensor, use the Tech 2 and build as follows: Body > Body Control Module > Data Display > Theft Data. View the three parameters for "CTD Trigger History" to see what triggered the alarm. If the trigger is the inclination sensor, inspect the sensor's mounting location. If it is attached to the driver's side lower HVAC duct, it will need to be relocated.

The location of the sensor placement has been updated to the top of the BCM bracket. See picture below. Relocate the sensor to the top of the BCM bracket as shown in the attached:



Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
-----------------	-------------	------------

*C9545	Relocate Inclination Sensor	0.5
* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION