



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Additional Information For HSLAN Diagnostics

Models: 2012 - 2014 Chevrolet Sonic

This PI was superseded to update model years. Please discard PIC5747.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Upon diagnosis of the HSLAN circuits 2500 & 2501 and performing a resistance test a technician may find he has approximately 58.5 Ohms of resistance across pins 6 & 14 of the ALDL. Upon further diagnostics when splitting the HSLAN a technician will find approximately 110 ohms on the EBCM side of the circuits (with the EBCM connected) and approximately 121 Ohms on the other side. With the EBCM disconnected there is approximately 121 Ohms on both sides of the HSLAN.

Recommendation/Instructions

Important: Do NOT replace the EBCM for this concern.

This is a normal reading. It has identified that, on the Sonic, there is approximately 1200 Ohms of resistance across the EBCM Pins 14 & 26 - causing the difference in the resistance readings on the HSLAN Circuits 2500 & 2501.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION