Bulletin No.: PI1032

GM S

Service Bulletin

PRELIMINARY INFORMATION

Subject: Click Noise Heard from Front Compartment Area, Possible DTC P059F Set

Models: 2014 Chevrolet Spark EV

Condition/Concern

Some customers may comment on a clicking or popping noise coming from the front compartment area. DTC P059F may or may not be set.

This may be caused by the wiring harness that runs across the bumper support beam rubbing on the air shutter assembly as they open and close.


Recommendation/Instructions

Remove the front fascia. Refer to Front Bumper Fascia Replacement in SI.

Reposition the wiring harness by taping up the harness as shown below. Once the front fascia assembly is installed, the harness will be supported by the shutter housing.




This condition may be caused by the harness dropping down during installation of the front fascia and causing the air shutter housing to be pushed down and contact the louvers when opening or closing.



The above graphic shows the pinched portion of the harness where it has dropped down and pushed on top of the louver housing causing contact.



The above graphic shows where the harness should be positioned to not contact the air shutter louvers.



The above graphic shows the view of the correct location of the taped up harness on the support.



The above graphic shows a closer view of the taped harness to the support.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1480108*	Reposition Wiring Harness	1.1 hrs

^{*}This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

