A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the <u>Elsa Newsletter</u> section in the Technician References menu.



Audi Elsa Newsletter

Edition 64: December 2, 2013

Content

- ElsaPro Tip "Save"
 Your Job
- Technical Bulletins
- Pending ServiceSolutions
- <u>Campaigns</u>
- Updates
- Suggestions



ElsaPro Tip - "Save" Your Job

Don't forget to hit the *Save* button after submitting a VIN in ElsaPro! A job is not officially created until either the *Save* button is clicked or an infomedia button is clicked.

Caution: Clicking a link on the system menu will display vehicle info, but will NOT save the job.

For more detail, a Job Aid has been published on ServiceNet under *Technician**References > ElsaPro Job Aids > ElsaPro Save Your Job

Technical Bulletins

44 Steering wheel shimmy, vibration and/or oscillation (2022563/8)			
Model(s)	Year	Vehicle Specific Equipment	
All	2008-2014	Not Applicable	

Condition: Customer feels vibration in the seat, vehicle floor, footwell, pedals, or steering wheel. This condition does not lead to any handling concerns or loss of vehicle control. The customer feels the vibration while driving at highway speeds from 55 – 80 mph (88 – 128 km/h).

Production Solution: Not applicable.

01 MIL on and/or oil pressure warning on (DTC P164D00) (2021418/5)			
Model(s)	Year	Vehicle Specific Equipment	
Q5	2009	3.2 FSI Engine	

Condition:

- MIL on.
- One or both of the following DTCs are stored in the engine control module:
 - DTC P0456: EVAP Emission Contr. Sys. (very small leak) Leak
 Detected
 - DTC P0442: EVAP Emission Contr. Sys. (small leak) Leak
 Detected
 - No leaks are found in the EVAP system.

Production Solution: New software in the engine control module, J623, addressed the condition.

01 MIL on and/or oil pressure warning on (DTC P164D00) (2033379/2)				
Model(s)	Year	Vehicle Specific Equipment		
A6, A7, S4, S5, S5 Cab, Q7, Q5	2013	3.0 FSI Engine		

Condition:

- The following DTC is stored in the engine control module:
 DTC P164D00: Oil pressure switch for reduced oil pressure malfunction
 - Red oil pressure warning light may be on.

Production Solution: Improved oil filter.

02 Rattle noise from rear of transmission at idle (2031910/2)			
Model(s)	Year	Vehicle Specific Equipment	
R8	2008-2014	Not Applicable	

Condition: Customer may report hearing a rattle noise from the rear of transmission at idle. On manual vehicles, the noise may change when clutch is depressed.

Production Solution: Not applicable.

46 Squealing from front brakes (PR-1LA or 1LB) (2033674/5)			
Model(s)	Year	Vehicle Specific Equipment	
A4	2009–2013	2.0T engine	
A5	2008-2013	2.0T engine	
A5 Cab	2010-2013	2.0T engine	
A6	2012-2013	2.0T engine	

Condition: Brakes on vehicles produced before September 3, 2012 (calendar week 36 of 2012), squeak or squeal when used with light to moderate force.

Production Solution: From September 3, 2012 (calendar week 36/2012), anti-seize lubricant was applied to the caliper carrier guide pins during production.

Pending Service Solutions

No new pending service solutions this week.

Back to top

Campaigns

No new campaigns this week.

Back to top

Updates

No new updates this week.

Back to top

Suggestions

Please send comments or suggestions to: aoa.workshopinformation@audi.com

Back to top

© 2013 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.