

Technical Service Bulletin

85 Fresh air blower is inoperative

85 13 16 2033596/1 April 19, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4	2009 - 2011	000001 - 999999		
A4 Ingolstadt	2012	000001 - 096029		
A4 Neckarsulm	2012	00001 - 015389		
A5	2008 - 2011	000001 - 999999		
A5	2012	000001 - 016109	Not applicable	
Q5	2009 - 2011	000001 - 999999		
Q5	2012	000001 - 060834		
A5 Cab	2010 - 2011	000001 - 999999		
A5 Cab	2012	000001 - 003976		

Condition

The fresh air blower is inoperative. One or more of the following DTCs may be stored in the heating and air conditioning electronics control module (address word 08):

- DTC 01844 004 (Control module for fresh air blower J126 No signal/communication)
- DTC 01844 014 (Control module for fresh air blower J126 Faulty)
- DTC 01273 009 (Fresh air blower -V2- Open / Short circuit to ground)
- DTC 01273 006 (Fresh air blower -V2- Short circuit to B+)

Audi

Technical Service Bulletin

Technical Background

Malfunctions of the fresh air blower could be caused by one or both of the following root causes:

- A faulty printed circuit board in the fresh air blower control module, J126.
- The carbon brushes bind in the brush holder and, as a consequence, lose contact with the motor commutator
 of the fresh air blower, -V2-.

Production Solution

- Improved fresh air blower control module, J126.
- Improved brush assembly has been implemented in production.

Service

If either of the following DTCs are present, replace the fresh air blower control module, J126:

- DTC 01844 004 (Control module for fresh air blower J126 No signal/communication)
- DTC 01844 014 (Control module for fresh air blower J126 Faulty)

-OR-

If either of the following DTCs are present, replace the fresh air blower, -V2-:

- DTC 01273 009 (Fresh air blower -V2- Open / Short circuit to ground)
- DTC 01273 006 (Fresh air blower -V2- Short circuit to B+)

If DTCs for both the J126 as well as the V2 are present, replace both the fresh air blower control module, J126 and the fresh air blower, -V2-.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	8530				
Damage Code:	0040				
Labor Operations:	Blower remove and reinstall	8530 1900	70 TU		
	-or-				
	Blower regulator remove and reinstall	8778 1900	70 TU		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 30 TU)		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online	e for DADP allowance	e details)		
Claim Comment:	As per TSB #2033596/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Part Number	Part Description	Quantity			
8K1820021C	Fan	1			
-OR-					
8K0820521B	Blower control	1			

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.