

94 Headlight cracked / water ingress into headlight lens

94 13 25 2034735/1 July 24, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A6	2012-2013	All	Xenon or LED Headlights	
A6	2014	000001-026800	Xenon or LED Headlights	

Condition

Customer Complaint:

 Heavy condensation present in the headlight (Figure 1).

Tip: Reference TSB 2012749, *94 Exterior lights, moisture accumulation.* Headlights that are applicable to TSB 2012749 do not apply to this bulletin unless cracking is present.



Figure 1. Headlight with heavy condensation

• Lower headlight lens cracking (Figure 2 and Figure 3).



Figure 2. Lower headlight lens cracking.





Figure 3. Lower headlight lens cracking.

• Upper headlight housing cracking (at transition from lens to black surround) (Figure 4 and Figure 5).



Figure 4. Upper headlight housing cracking.





Figure 5. Upper headlight housing cracking.

Workshop Findings:

- No visible external force marks (from accident or flying debris) are present.
- One or both sides may be affected.
- The vehicle is *not* equipped with halogen headlights.

Technical Background

The production process causes stress on the headlights from the bumper, as well as torsion force from installation.

The moisture is an optical condition that does not affect the function or performance of the headlights and it will not lead to corrosion or damage of the internal headlight parts.

Production Solution

Improved tempering of headlight glass.



Service

Replace the affected headlight with the new part number:

Vehicle Equipment	Side	Old Part Number	New Part Number
	Driver:	4G0941773B	4G0941773E
LED Headlights	Passenger:	4G0941774B	4G0941774E
Xenon Headlights w/AFS	Driver:	4G0941753A	4G0941753D
(PR No. 8Q5 / 8Q7)	Passenger:	4G0941754A	4G0941754D
Xenon Headlights w/o AFS	Driver:	4G0941043B	4G0941043E
(PR No. 8Q3)	Passenger:	4G0941044B	4G0941043E



Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	9415				
Damage Code:	0015				
Labor Operations:	Remove and Install front bumper	6329 1900	90 TU		
	Remove and install one headlight	9415 1951	30 TU		
	-or-				
	Remove and install two headlights	9415 2051	50 TU		
	Adjust headlights	9415 1950	20 TU		
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	No allowance	о ти		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2034735/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Required Parts and Tools

Vehicle Equipment	Side	Old Part Number	New Part Number
	Driver:	4G0941773B	4G0941773E (if necessary)
LED Headlights	Passenger:	4G0941774B	4G0941774E (if necessary)
Xenon Headlights w/AFS	Driver:	4G0941753A	4G0941753D (if necessary)
(PR No. 8Q5 / 8Q7)	Passenger:	4G0941754A	4G0941754D (if necessary)
Xenon Headlights w/o AFS	Driver:	4G0941043B	4G0941043E (if necessary)
(PR No. 8Q3)	Passenger:	4G0941044B	4G0941043E (if necessary)

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2012749, 94 Exterior lights, moisture accumulation

All parts and service references provided in this TSB (2034735) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.