



Audi side assist update

Contents: Technical actions

No. Event	Topic	Type/model
1	Latest information about Audi side assist	All

=> Several TSBs have been released recently addressing potential customer concerns – it is imperative to follow the TSB related to the specific customer concern!



Audi side assist

System sporadically inoperative

- ► Side assist deactivates itself after the engine starts (A4 PI, A5 PI, Q5 PI)
 - ▶ DTC for "Lane change assistance control module 2 Function limitation due to insufficient voltage" stored in the side assist control unit (diagnosis address 3C)
 - Update software as per TSB 2031095
- ► Side assist inoperative (A6, A7, A8)
 - ► DTC for "Lane Change Assistance Warning Lamp -K233- / -K234- Open/Short Circuit to B+" stored in the side assist control unit (diagnosis address 3C)
 - ► Update software as per TSB **2034000**

Audi side assist

System sporadically inoperative

- ► Side assist inoperative with "Sensors blocked" warning (A4 PI, A5 PI)
 - ▶ DTC for "Lane change assistance control module Restricted view" stored in the side assist control unit (diagnosis address 3C)
 - Follow instructions in PSS TSB 2033943
- ► Side assist inoperative (A4 PI, A5 PI, Q5 PI, A6, A7)
 - ▶ DTC for "Lane Change Assistant Control Module -J769 No signal/communication" or "Data-Bus distance regulation No signal/communication" stored in the gateway (diagnosis address 19) and/or DTC for "Local data bus Faulty, stored in the lane change assist (diagnosis address 3C)
 - Replace control unit(s) as per TSB 2032225



Audi side assist

False warnings

- ► False warnings from Audi side assist (A6, A7)
 - ► Update software as per TSB **2028809**
- ► False warnings from Audi side assist (A4 PI, A5 PI)
 - ► Cause:
 - ▶ Vibrations as a result of broken/loose parts inside the bumper (A4 PI, A5 PI)



- ► Faulty radar reflections caused by wheels/tires (allroad only)
- ► Follow instructions in TSB **2030583** (A4, A5) or TSB **2033782** (allroad)