Audi

Technical Service Bulletin

01 MIL on (DTC P2006(00) or P2007(00) stored in ECM)

01 13 03 2033919/3 May 29, 2013. Supersedes Technical Service Bulletin Group 01 number 13-02 dated May 29, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6/A7, S4, S5, S5 Cab, Audi Q7, Audi Q5	2013	All	3.0 FSI Engine

Condition

REVISION HISTORY				
Revision	Date	Purpose		
3	-	Revised header data (updated engine codes)		
2	5/29/13	Revised Service (Added steps and image)		
1	5/16/2013	Initial publication		

- MIL on.
- One or both of the following DTCs is stored in the engine control module, J623 (address word 01):
 - DTC P2006(00) (Intake Manifold Runner Control Stuck Closed, Bank 1).
 - DTC P2007(00) (Intake Manifold Runner Control Stuck Closed, Bank 2).
- There may be slight power reduction at high RPMs.

Technical Background

One of the vacuum actuators on intake runner bank 1 or bank 2 is defective.

Production Solution

Updated vacuum actuator.

Audi

Technical Service Bulletin

Service

 Identify the defective vacuum actuator. Use Guided Fault Finding (GFF), or use the vacuum pump (Figure 1) to determine which actuator is defective.

Tip: Even though only one actuator is defective, a large leak in the defective actuator may cause DTCs to be set for **both** banks because both are fed from the same vacuum solenoid. Ensure that the defective actuator is correctly identified.




Figure 1. Vacuum pump VAS 6213

- 2. Replace the defective actuator using instructions from ElsaWeb. Do not replace the entire intake runner.
- Important: Record the production date of the defective vacuum actuator, which is shown in the German date format (dd.mm.yy) (Figure 2). Call TAC (Technical Assistance Center) and provide them with the production date of the actuator and the part number needed for the repair.



Figure 2. Production date shown in German format.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. Service Bulletin is informa		any warranty, this Technical	
Service Number:	2447			
Damage Code:	0010			
Labor Operations:	Compressor remove+reinstall			
	For S4, S5, S5 Cab, and Audi Q5	2114 1941	190 TU	
	For A6, A7, and A8	2114 1941	160 TU	
	For Audi Q7	2114 1939	160 TU	
	Intake runner remove+reinstall, replace actuator			
	For S4, S5, S5 Cab, and Audi Q5	2447 1991	40 TU	
	For A6, A7, and A8	2447 1991	40 TU	
	For Audi Q7	2447 1989	40 TU	
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (max 20 TU)	
	Road test prior to service procedure	No allowance	0 TU	
	Road test after service procedure	0121 0004	10 TU	
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)			
Claim Comment:	As per TSB # 2033919/3			

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Part number	Part Description	Quantity
06E133159J	Actuator left (replace only the affected actuator)	1
06E133159H	Actuator right (replace only the affected actuator)	1
06E998907D	Repair kit	3
079129717B	Gasket	3
079129717D	Gasket	3
06E103213	Tube	1
G 012A8G1G	Coolant top off	0.3

Tool Number	Tool Description
VAS 6213	Vacuum pump

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.