



Countries:	CANADA, UNITED STATES, MEXICO	Document ID:	IK1200873
Availability:	ISIS	Revision:	1
Major System:	ENGINES	Created:	1/17/2013
Current Language:	English	Last Modified:	5/10/2013
Other Languages:	NONE	Author:	Charles Sun
Viewed:	341		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 10	 0

Title: Washers addition to water pump pulley bolts

Applies To: MaxxForce® DT, 9, & 10 EPA 10

DESCRIPTION

There have been some cases reported of water pump pulleys loosening on the MaxxForce® DT, 9, & 10 EPA 10. When this occurs, it is often caused by friction between the bottom of the hex head and the powder coated surface of the pulley. When the bolt is tightened to specification, this excessive friction will cause the bolt not to receive proper tension.

RESOLUTION

When the four bolts on water pump pulley are removed,

- Replace each of them with a new M6 x 14 bolt with captured washer. PN: 7094018C1
- Torque specification: 133 lbf-in (15 N·m)

Please be informed that this specification supersedes the standard torque recommendation in [2010 MaxxForce® DT, 9, and 10 Engine Service Manual EGES 450](#).



Hide Details

Feedback Information

Viewed: 340

Helpful: 10

Not Helpful: 0

No Feedback Found

Copyright © 2013 Navistar, Inc.