T-SB-0039-13

Rev1

March 6, 2013



# **Blind Spot Monitor DTC C1AB4/C1AB5**

Service

Category Audio/Visual/Telematics

Section

Park Assist/Monitoring

Market USA



### **Applicability**

YEAR(S)	MODEL(S)	E	ADDITIONAL INFORMATION	
2013	Avalon HV			
2013	Avaion			

#### **REVISION NOTICE**

April 19, 2013 Rev1:

The Production Change Information section has been updated.

Any previous printed versions of this bulletin should be discarded.

#### Introduction

Some 2013 model year Avalon and Avalon HV vehicles may display a "Check Blind Spot Monitor System" message on the multi-information display with Diagnostic Trouble Code (DTC) C1AB4 and/or C1AB5 stored. The procedure in this bulletin has been developed to address this condition.

### **Production Change Information**

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	GRADE	PLANT PRODUCTION CHANGE EFFECTIVE VIN	
Avalon	Limited		4T1BK1EB#DU007805
Avaion	Touring	TMMK	4T1BK1EB#DU007797
Avalon HV	Touring		4T1BD1EB#DU002034
Avaion nv	Limited		4T1BD1EB#DU002043



### **Warranty Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EL1302	Repair Wire Harness (Both Sides)	1.0	87901-07020 87901-07030 87906-07060 87906-07050	72	71

#### APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

#### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
_	82999-52010	Sleeve	2
_	82999-30010	Thermo Contact Tube	3

#### Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Wire Crimper (Non Insulated)*	<u>09042-2C100</u>	1

#### NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*		TS2UNIT	
TIS Techstream	ADE	TSPKG1	1
Techstream Lite		TSLITEDLR01	]

#### NOTE

- Only ONE of the Techstream units listed above is required.
- · Software version 8.10.021 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

<sup>\*</sup> Essential SST.



#### **Inspection Procedure**

Using Techstream, check for stored DTCs. Confirm one of the following DTCs is present:

- C1AB4 Open in Outer Mirror Indicator (Master)
- C1AB5 Open in Outer Mirror Indicator (Slave)

If DTC C1AB4 or C1AB5 is stored as a current or history DTC, complete the Repair Procedure to BOTH outer side rear view mirror assemblies.

If DTC C1AB4 or C1AB5 is NOT stored as current or history, STOP! This bulletin does NOT apply.

Refer to the Technical Information System (TIS), applicable model and model year Repair Manual:

- 2013 Avalon: Audio/Visual/Telematics – Park Assist / Monitoring – "Park Assist / Monitoring: Blind Spot Monitor System: <u>Problem Symptoms Table</u>"
- 2013 Avalon HV: Audio/Visual/Telematics – Park Assist / Monitoring – "Park Assist / Monitoring: Blind Spot Monitor System: Problem Symptoms Table"

#### Repair Procedure

The following repair procedure will instruct how to remove the Blind Spot Monitor (BSM) indicator ground circuit from the harness and splice it into the Mirror Heater ground circuit.

#### NOTE

- Use the same procedure for both the RH and LH sides.
- · The procedure described below is for the LH side.
- 1. Remove outer rear view mirror cover.

Refer to TIS, applicable model and model year Repair Manual:

- 2013 Avalon:
  Vehicle Exterior Mirror (Ext) "Mirror (Ext): Outer Rear View Mirror Cover: Removal"
- 2013 Avalon HV: Vehicle Exterior – Mirror (Ext) – "Mirror (Ext): Outer Rear View Mirror Cover: Removal"
- 2. Remove the tape from the two wire BSM indicator wire harness.



Tape Location


### Repair Procedure (Continued)

**TOYOTA** 

3. Measure 20 mm (0.79 in.) from the junction of the mirror harness and cut the YELLOW wire.

#### NOTE

Mirror removed for illustration purposes only. Mirror does NOT need to be removed from vehicle.



**Cut Location** 

4. Remove 8 mm (0.32 in.) of insulation from the end of the YELLOW BSM indicator ground wire leading to the connector.

Figure 3.



### Repair Procedure (Continued)

**TOYOTA** 

5. Install a barrel sleeve on to the end of the indicator Figure 4. ground wire.

#### NOTE

Ensure wire is fully inserted into the sleeve.





Figure 5.



1	Sleeve
2	Wire Stop

6. Place the sleeve into the 1.25 mm (0.05 in.) crimp Figure 6. die of the SST.

#### NOTE

- Place the sleeve into the SST so that the split in the sleeve is in the half circle of the SST.
- SST 09042-2C100 is the only tool approved to perform this repair. Do NOT use any other tool to crimp the sleeve.

#### Repair Procedure (Continued)

**TOYOTA** 


7. With the sleeve correctly placed in the SST and wire fully inserted into the sleeve, crimp one side of the sleeve in the area shown by closing the handles fully until they release. Crimp the sleeve onto the BSM indicator ground wire.

#### NOTE

SST 09042-2C100 is the only tool approved to perform this repair. Do NOT use any other tool to crimp the sleeve.


8. Install thermo tubing onto the BSM indicator ground wire.

Figure 7.



1 | Crimp This Portion

Figure 8.



Locate the Mirror Heater ground wire (Brown w/Yellow). Measure 30 mm (1.18 in.) from the wire harness junction and cut the wire.

Figure 9.



Cut Location

### Repair Procedure (Continued)

**TOYOTA** 

10. Remove 8 mm (0.32 in.) of insulation from both cut ends of the Mirror Heater ground wire.

Figure 10.




11. Insert both ends of the Mirror Heater ground wire (Brown w/Yellow) into the remaining open end of the barrel sleeve and crimp using the SST.

### NOTE

Do NOT twist ends of the wire together before inserting into the barrel sleeve.


Figure 11.



1	Sleeve
2	Wire Stop
3	Wires

12. Lightly tug on each connection to ensure that the wire is securely crimped.

Figure 12



### **Repair Procedure (Continued)**

**TOYOTA** 

13. Position the thermo tube 8 mm (0.32 in.) past the end of the barrel sleeve.

Figure 13.

# **TOYOTA**

# **Blind Spot Monitor DTC C1AB4/C1AB5**

### Repair Procedure (Continued)

14. Using a heat gun, heat the thermo tubing until it shrinks and seals the repaired connection.


#### NOTICE

- When using the heat gun, keep the heat gun about 100 mm (0.39 in.) to 200 mm (7.8 in.) from the thermo tubing.
- Protect the surrounding areas (i.e., mirror assembly, interior panels, and door) from heat damage.

#### **NOTE**


During the sealing process, adhesive may seep from the thermo tubing. This is a normal condition and part of the sealing properties of the thermo tube.

Figure 14.



1 100 mm (3.9 in.) to 200 mm (7.8 in.)

Figure 15.




Adhesive

#### Repair Procedure (Continued)

- 15. Use the thermo tube to seal the cut end of the BSM ground wire at the wire harness junction.
  - A. Cut a thermo tube in the center to make two 30 mm (1.18 in.) pieces. (Use one piece for each side.)
  - B. Place thermo tube on cut wire end, leaving the tube extending 8 mm (0.32 in.) past the end of the wire.

Figure 16.



C. Using a heat gun, heat the thermo tubing until it shrinks and seals the wire end.

#### NOTICE

- When using the heat gun, keep the heat gun about 100 mm (0.39 in.) to 200 mm (7.8 in.) from the thermo tubing.
- Protect the surrounding areas (i.e., mirror assembly, interior panels, and door) from heat damage.

#### NOTE

During the sealing process, adhesive may seep from the thermo tubing. This is a normal condition and part of the sealing properties of the thermo tube.

### **Repair Procedure (Continued)**

**TOYOTA** 

16. Insulate the BSM indicator wire harness by wrapping with electrical tape.

Figure 17.

17. Install outer rear view mirror cover.

Refer to TIS, applicable model and model year Repair Manual:

- 2013 Avalon: Vehicle Exterior Mirror (Ext) "Mirror (Ext): Outer Rear View Mirror Cover: <u>Installation</u>"
- 2013 Avalon HV: Vehicle Exterior Mirror (Ext) "Mirror (Ext): Outer Rear View Mirror Cover: Installation"
- 18. Verify Blind Spot Monitor Mirror indicators operate normally.
- 19. Clear Blind Spot Monitor System DTCs with Techstream.