



Service Bulletin

PRELIMINARY INFORMATION

Subject: Passenger Side Defrost Air Flow/Performance and/or Temperature Less Warm Than Drivers Side in Defrost, IP Vent or Heat Modes

Models: 2012-2013 Cadillac Escalade Models
2012-2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe
2012-2013 GMC Sierra, Sierra Denali, Yukon Models
Excluding Crew Cab and Extended Cab with Single Zone Air Conditioning (RPO C67)

Condition/Concern

Some customers may comment that the passenger side defrost air flow/performance and/or the temperature is less warm than the drivers side in defrost, IP vent or heat modes. Even with this condition, the vehicle will meet all requirements.




The cause of this condition may be that the belt seal (1) that goes around the heater core may have become mis-positioned. If this occurs, it can create a path for air to travel to the wrong side of the HVAC Module.

Recommendation/Instructions

Preliminary Inspection Procedure


The intent of this inspection procedure is to gain visual access to the heater core belt seal without removing the IP, HVAC module and heater core. Visual access to the heater core is attained by drilling a hole in the lower HVAC case and using a borescope, or equivalent, following the steps below.




1. Remove the instrument panel insulator (1). Refer to Instrument Panel Insulator Replacement in SI.




2. If equipped, remove the left side front floor console side trim panel (1). Refer to Front Floor Console Side Trim Panel Replacement - Left Side in SI.




3. Remove the instrument panel lower brace bezel and center support bracket (1). Refer to Instrument Panel Center Support Bracket Replacement in SI.



Important: The mark for the hole location should be in line with the standing rib on the bottom side of the HVAC case.




4. Note the position of the lower HVAC case and mark a location to drill a hole in the case on the rounded corner facing the driver footwell area. The mark should be approximately 13 mm (0.50 in) upward from the bottom surface of the case.




Important: Set the drill stop 19 mm (0.75 in) from the point of the drill bit to prevent drilling too deep and possibly damaging the heater core.


5. Using a 3/8" drill bit with a stop, set at max 3/4" depth hole, drill an access hole (1) at the marked location on the case.



6. Insert the borescope (1) and look to see the position of the horizontal belt seal around the heater core.



- If the belt seal (1) is rolled or mis-positioned (as shown in the graphic above), install the push pin to the drilled access hole in the HVAC case as described in step #7, then R&R the heater core and replace the heater core belt seal following Heater Core Replacement in SI.
- If the belt seal is properly positioned, complete steps #7-10, then refer to SI for any further recommended HVAC diagnostics.



Important: To improve sealing of the plugged hole, apply a small amount of RTV, GM P/N 12378521 (in Canada, P/N 88901148), or equivalent, to the push pin prior to installation.

7. Install a push pin (1), Kent Automotive Push Retainer P/N P20681, or equivalent, into the access hole drilled into the HVAC case.
8. Install the instrument panel center support bracket and the lower brace bezel. Refer to Instrument Panel Center Support Bracket Replacement in SI.
9. If equipped, install the left side front floor console side trim panel. Refer to Front Floor Console Side Trim Panel Replacement - Left Side in SI.
10. Install the instrument panel insulator. Refer to Instrument Panel Insulator Replacement in SI.

Parts Information

Part Number	Description
P20681	*Kent Automotive Push Retainer
89018784	SEAL KIT, HTR & A/C EVPR & BLO MDL
*We believe this source and their products to be reliable. There may be additional manufacturers of such products/materials. General Motors does not endorse, indicate any preference for, or assume any responsibility for the products or material from this firm or for any such items that may be available from other sources.	

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4480038*	Preliminary Heater Core Seal Inspection Procedure	0.5 hr
4413660	Heater Core Replacement	Use Published Labor Operation Time
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION