Malfunctions of various control units and/or on-board power supply problems caused by water in the control unit tray under the driver/front passenger seat (dislocated, pinched or leaking condensation hose)

Topic number	LI83.00-P-052510	
Version	3	
Design group	83.00 General	
Date	02-22-2013	
Validity	All Mercedes-Benz cars	
Reason for change	Remedy adapted, validity adapted	
Reason for block		

Complaint:

Water that enters into the control unit tray under the driver/front passenger seat can damage the control units installed there and complaints may be received about the functions associated with these control units.

Problems with the on-board power supply voltage may also occur.

Cause:

The condensation hose (right/left) on the A/C housing may either be dislocated, pinched/crushed (water collects in A/C housing) or leaking, resulting in water entering the interior.

Remedy:

If the condensation hose (right/left) is dislocated, push it all the way back onto the outlet fitting of the A/C housing and check for tight seating by pulling gently. If necessary, use a cable tie to additionally fix the condensation hose in place. Never use soapy water or silicone spray to install.

If the condensation hose (right/left) is pinched/crushed, it can be checked for free passage as follows:

1. Use the operating unit to set maximum cooling on both sides.

2. On the vehicle underside, check whether water emerges from the condensation water drains. If no water emerges, the hose is blocked. In this case, reposition the hose correctly to ensure free passage or replace the hose if it is damaged.

Invoice the damage with reference to the appropriate damage code..

Symptoms
Communication/information / Entertainment / Radio / Cuts out intermittently
Communication/information / Entertainment / Audio / Tone setting malfunction
Communication/information / Entertainment / Audio / Volume adjustment function error
Communication/information / Entertainment / Audio / Speakers emit no sound
Communication/information / Entertainment / Audio / Speakers emit interference noise
Communication/information / Entertainment / Audio / Poor audio quality
Communication/information / Entertainment / Audio / Several speakers are nonfunctional
Communication/information / Entertainment / Radio / No audio

XENTRY

Communication/information / Entertainment / Radio / Bad sound quality

Communication/information / Entertainment / Audio / Misfire

Overall vehicle / Lighting / Exterior lights / Driving lights / Low beams / Low beam function / Nonfunctional

Overall vehicle / Lighting / Exterior lights / Driving lights / Headlamp range adjustment / Nonfunctional

Power generation / Engine management / Engine start/stop / Does not start

Work units				
Op. no.	Operation text	Time	Damage code	Note
			83E01 38	Left condensation drain hose loose
			83T01 38	Right condensation drain hose loose
			83E01 C6	Left condensation drain hose kinked
			83T01 C6	Right condensation drain hose kin- ked
			83E01 04	Left condensation drain hose leaking
			83T01 04	Right condensation drain hose lea- king
			83493 38	Condensation drain hose loose
			83493 C6	Condensation drain hose kinked

Vehicle	Engine	Transmission
A (168)	*	*
A (169)	*	*
A (176)	*	*
B (245)	*	*
B (246)	*	*
C (203)	*	*
C (204)	*	*
CL (215)	*	*
CL (216)	*	*
CLA (117)	*	*
CLK (208)	*	*
CLK (209)	*	*
CLS (218)	*	*
CLS (219)	*	*
E (207)	*	*
E (210)	*	*
E (211)	*	*
E (212)	*	*
G (460)	*	*
G (461)	*	*

XENTRY

G (463)	*	*
GL (164)	*	*
GL (166)	*	*
GLK (204)	*	*
M (163)	*	*
M (164)	*	*
M (166)	*	*
R (251)	*	*
S (220)	*	*
S (221)	*	*
S (222)	*	*
SL (230)	*	*
SL (231)	*	*
SLK (170)	*	*
SLK (171)	*	*
SLK (172)	*	*
SLS (197)	*	*