Bulletin No.: 08-06-01-006D

Date: May-2013

# **Service Bulletin**

## **TECHNICAL**

Subject: Engine Squealing Type Noise on Start-up or Vibration

Models: 2007 Buick Rendezvous

2007-2008 Buick Terraza

2007 Chevrolet Monte Carlo

2007-2009 Chevrolet Uplander

2007-2010 Chevrolet Malibu

2007-2011 Chevrolet Impala

2007-2009 Pontiac Montana SV6

2007-2010 Pontiac G6

2007-2008 Saturn Relay

2007-2009 Saturn AURA

2007-2010 Saturn VUE

Equipped with 3.5L or 3.9L Engine (VINs N, K, R, W, 1, 3, 8 - RPOs LZ4, LZE, LZ8, LGD, LZ9, LZG, LX9)

This bulletin is being revised to add the 2008-2011 model years to the applicable vehicles. Please discard Corporate Bulletin Number 08-06-01-006C.

#### Condition

Some customers may comment on a squealing type noise coming from the engine compartment on start-up. Others may comment about an engine vibration.

#### Cause

The outer ring on the crankshaft balancer may be slipping on the center hub.

#### Correction

Inspect the crankshaft balancer to see if the outer ring is slipping on the center hub. If this condition is found, replace the crankshaft balancer using the applicable one listed in the parts catalog. Refer to Crankshaft Balancer Replacement in SI.

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4063290	Crankshaft Balancer Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

