

1 01 04-13



Service Information Bulletin

SUBJECT	DATE
SPN 1592/FMI 13 and 19– GHG14	January 2013

Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0084	GHG 14 DD Platform	SPN 1592/FMI 13 – GHG14	This is new information.
DDC-SVC-MAN-0084	GHG 14 DD Platform	SPN 1592/FMI 19 – GHG14	This is new information.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
 Telephone: 313-592-5000
www.demanddetroit.com

2 SPN 1592/FMI 13 - GHG14

This diagnostic is typically J1939 HRW (High Resolution Wheel Speed) Wheel Speed Signal Missing.

1. Connect DDDL/DDRS 7.08 SP2 or higher.
2. Check for multiple codes:
 - a. If Common Powertrain Controller (CPC4) SPN 168/FMI (any) (battery voltage) (Charging System) faults are present, troubleshoot these first.
 - b. If Controller Area Network (CAN) line faults SPN 625/FMI (any) are present, repair the Controller Area Network (CAN) line faults.
 - c. If only a J1939 Error fault is present, Go to step 3.
3. Has the Common Powertrain Controller (CPC4) been recently reprogrammed?
 - a. Yes; ensure the parameters are configured correctly for the vehicle application; refer to the Application and Installation Manual for the correct parameter configuration, if configuration is correct, refer to Original Equipment Manufacturer (OEM) material for J1939 troubleshooting for the affected module.
 - b. No; Go to step 4.
4. Turn the ignition OFF (key OFF, engine OFF) and disconnect DDDL/DDRS, Wait five minutes for all modules to power down.
5. Turn ignition ON (key ON, engine OFF).
6. Reconnect DDDL/DDRS 7.08 SP2 or higher. Are fault codes active?
 - a. Yes; Refer to section "SPN 625/FMI 9 – EPA10 - GHG14" for further PT CAN troubleshooting.
 - b. No; clear faults codes and release vehicle.

3 SPN 1592/FMI 19 – GHG14

This diagnostic is typically J1939 HRW (High Resolution Wheel Speed) Wheel Speed Signal Erroneous.

1. Connect DDDL/DDRS 7.08 SP2 or higher.
2. Check for multiple codes:
 - a. If Common Powertrain Controller (CPC4) SPN 168/FMI (any) (battery voltage) (Charging System) faults are present, troubleshoot these first.
 - b. If Controller Area Network (CAN) line faults SPN 625/FMI (any) are present, repair the Controller Area Network (CAN) line faults.
 - c. If only a J1939 Error fault is present, Go to step 3.
3. Has the Common Powertrain Controller (CPC4) been recently reprogrammed?
 - a. Yes; ensure the parameters are configured correctly for the vehicle application; refer to the Application and Installation Manual for the correct parameter configuration, if configuration is correct, refer to Original Equipment Manufacturer (OEM) material for J1939 troubleshooting for the affected module.
 - b. No; Go to step 4.
4. Turn the ignition OFF (key OFF, engine OFF) and disconnect DDDL/DDRS, Wait five minutes for all modules to power down.
5. Turn ignition ON (key ON, engine OFF).
6. Reconnect DDDL/DDRS 7.08 SP2 or higher. Are fault codes active?
 - a. Yes; Refer to section "SPN 625/FMI 9 – EPA10 - GHG14" for further PT CAN troubleshooting.
 - b. No; clear faults codes and release vehicle.