



This Service Information bulletin supersedes SI B61 20 13 **dated November 2013.**

PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS

NEW designates changes to this revision

SUBJECT

Service Action: Replace EMF Switch

MODEL

NEW F01

NEW F02

F15

SITUATION

An electrical malfunction in the EMF (Electromechanical Parking Brake) switch can cause an erroneous Check Control Message to be displayed. The parking brake functions properly.

CAUSE

EMF switch hardware error

AFFECTED VEHICLES

This Service Action involves **NEW** F01, F02 and F15 vehicles which were produced from June 2013 to October 2013.

In order to determine whether a specific vehicle has had this Service Action completed or is affected by this Service Action, first check the B-pillar label for code number **658**. If code number **658** has been punched out, the campaign has already been performed. If code number **658** has not been punched out, it will be necessary to utilize the "Service Menu" of DCSnet (Dealer Communication System) or the Key Reader. Based on the response of the system, either proceed with the corrective action or take no further action.

CORRECTION

Replace the EMF switch.

PROCEDURE

Replace the EMF switch per ISTA Repair Instruction 61 31 172, "Remove and install/replace the switch for the electromechanical parking brake (EMF)."

PARTS INFORMATION

The part numbers involved in this repair are blocked from Dealer ordering.

Stock on these parts are limited, so we've implemented a **VIN-specific parts ordering process.**

Please follow the ordering procedure outlined below:

All requests must be emailed to recallparts@bmwna.com. The email must contain the following information or the orders request will be cancelled:

Subject line – EMF Switch

Center number and location code where the part should be delivered

Contact Information – name, phone number

Part number required

VIN – Last seven digits (7)

Please only send one VIN per email.


Multiple requests for the same VIN will be cancelled.

Orders will be placed into the system between 10:00am and 6:00pm EST, using the last 7 digits of the VIN as the PO.

All orders will be placed as VOR in the order they are received. Orders received after local VOR cut off time will be shipped the following day.

Part Number	Description	Quantity
61 31 9 349 034	NEW (F15)Parking brake/Auto hold switch	1
NEW 61 31 9 159 997	(F01, F02) Parking brake/Auto hold switch	1

LABEL INSTRUCTIONS

	<p>This Service Action has been assigned code number 658. After the vehicle has been checked and/or corrected, obtain a label (SD 92-420) and:</p> <ol style="list-style-type: none"> Emboss your BMW center warranty number in the middle of the label (1); Punch out code number 658 (2), printed on the label; and Affix the label to the B-pillar as shown.
---	--

If the vehicle already has a label from a previous Service Action/Recall Campaign, affix the new label next to the old one. Do not affix one label on top of another one because a number from an underlying label could appear in the punched-out hole of the new label.

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following

information:

Defect Code:	00 61 88 03 00	
Labor Operation:	Labor Allowance:	Description:
00 61 863	NEW Refer to KSD2	Replace the switch for the electromechanical parking brake

Labor operation code 00 61 863 is a Plus labor operation.

NEW Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the “Search” button, and then enter the applicable flat rate labor operation in the FR code field.

[Copyright ©2013 BMW of North America, Inc.]