



SUBJECT

Integrated Owner's Manual No Longer Available After Programming

MODEL

F30

F31

F32

F34

SITUATION

After a programming or replacement of the Front Electronics Module (FEM), the customer states that the Integrated Owner's Manual (IBA) can no longer be selected in the vehicle.

CAUSE

FEM application error

PROCEDURE

1. Check and verify that the IBA is not available in the Central Information Display (CID).
2. Connect to the vehicle using ISTA/P 2.50.2 or higher, and import the vehicle order using the "Online" vehicle order import function, as seen below.

Vehicle order import

The following import sources are available for the vehicle order import:

Online

Exchange data carrier

Termination
Back
Continue

GRUSB6113-20

3. Once the vehicle order is successfully imported, perform a complete encoding of the vehicle.

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

For information on programming and coding with ISTA/P, refer to CenterNet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

4. After the coding is complete, let the vehicle enter sleep mode for approximately 15 minutes, and recheck that the IBA is properly displayed.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

Defect Code:	61 38 22 02 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults)
and if necessary, also		

61 21 528	Refer to KSD2	Charging battery
and		
61 00 730	Refer to KSD2	Programming/encoding control unit(s)

Labor operation code 00 00 006 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the “Search” button, and then enter the applicable flat rate labor operation in the FR code field.

[Copyright ©2013 BMW of North America, Inc.]