



**Countries:** CANADA, UNITED STATES, MEXICO  
**Availability:** ISIS, Bus ISIS, FleetISIS  
**Major System:** ENGINES  
**Current Language:** English  
**Other Languages:** [Français](#), [Español](#),  
**Viewed:** 1392

**Document ID:** IK1200471  
**Revision:** 4  
**Created:** 3/9/2010  
**Last Modified:** 8/26/2013  
**Author:** David Horner

[Less Info](#)

[Hide Details](#)

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  235	<b>Not Helpful</b>  212
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	---------------------------	-------------------------------

**Title:** MaxxForce® 11 and 13 Engine Harness Rubbing Oil Dipstick Tube

**Applies To:** 2008- 2009 MaxxForce® 11 and 13 Engines

## DESCRIPTION

Engine Harness rubbing oil dipstick tube assembly.

## SYMPTOMS


- Engine may have intermittent issues and diagnostic codes and /or intermittently trip the ECM Circuit Breaker or Fuse.

## POSSIBLE DIAGNOSTIC TROUBLE CODES

Any number of engine codes could become active if this issue occurs.

## DIAGNOSTICS

Visually inspect for rubbing/chaffing of the engine harness at the engine oil dipstick tube.



**Photo 1 - Harness contact with Dipstick Tube**



**Photo 2 - Example harness and wire damage**

## SERVICE PROCEDURE

If no damaged has occurred secure the harness away from the dipstick tube using tie straps and hose guide part number 3804604C1 as illustrated in the photo below. If damage has occurred start a case file through Tech Services and attach pictures of damage so the appropriate plan of action can be determined.



PN 3804604C1

 Hide Details

Feedback Information

Viewed: 1391

Helpful: 235

Not Helpful: 212

No Feedback Found