



<b>Countries:</b>	CANADA, UNITED STATES	<b>Document ID:</b>	IK1600019
<b>Availability:</b>	ISIS	<b>Revision:</b>	3
<b>Major System:</b>	CAB / SLEEPER / HOOD	<b>Created:</b>	6/27/2007
<b>Current Language:</b>	English	<b>Last Modified:</b>	8/13/2013
<b>Other Languages:</b>	<a href="#">Français</a> , <a href="#">Español</a> ,	<b>Author:</b>	Gregory Mackey
<b>Viewed:</b>	400		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 <a href="#">View My Bookmarks</a>				 78	 112

**Title: Headlight Housing Moisture Dissipation TSI 070804**

**Applies To: 4100, 4200, 4300, 4400, 8500, 8600, BE 200, CE 200, CE 300, HC Bus, LC Bus, RXT End Date: 05/03/2007**

**DESCRIPTION**

Moisture collection inside a composite headlight is normal and can be dissipated by operating the lights for approximately 15 minutes. However, in certain environmental conditions, the composite headlights can collect an excessive amount of moisture inside the lens which cannot be dissipated by regular use. To prevent this, Install Gore-Tex patches at the three venting locations by following these instructions.

[Click here for instructions TSI 070804](#)

**PARTS INFORMATION**

**2593399C91 Headlight Vent Gore-Tex Patch Kit 1**

Hide Details

Feedback Information

Viewed:	399
Helpful:	78
Not Helpful:	112
No Feedback Found	