



<b>Countries:</b>	AUSTRALIA, CANADA, UNITED STATES, MEXICO, SOUTH AFRICA	<b>Document ID:</b>	IK1200818
<b>Availability:</b>	ISIS, FleetISIS	<b>Revision:</b>	6
<b>Major System:</b>	ENGINES	<b>Created:</b>	9/19/2012
<b>Current Language:</b>	English	<b>Last Modified:</b>	3/28/2013
<b>Other Languages:</b>	NONE	<b>Author:</b>	Anthony Stover
<b>Viewed:</b>	1218		

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  32	<b>Not Helpful</b>  1
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-----------------------------

**Title: Oil Ingestion (intake) - Component Inspection and CAC cleaning procedure**

**Applies To: MaxxForce 11, 13,15L All emissions levels ( 2007 thru current)**

**DESCRIPTION**

Engine over speed due to oil ingestion from a turbo failure.

- May or may not have resulted in engine damage (i.e. piston to valve contact, failed connecting rod, etc..)
- **Technical support case file must be opened.** If an OnCommand customer, please direct the Repair Advocate to involve the engine technical support group.

**RESOLUTION**

Charge Air Cooler (CAC) must be removed and cleaned thoroughly. After cleaning the CAC, allow the CAC to drain by turning it vertically (inlet or outlet pipe is closes to the floor). This will help ensure any remaining oil drains out through either of the air ports.

Replace the failed turbo(s)

**\*\*\*\*Note: Severe Service chassis's have 2 CAC's on the cooling package ( one on the front and another on the back). Both will need to be cleaned.**

**\*\*\*Warning: Failure to clean out the CAC(s), can result in another over speed event. This may result in a non-warranty repair for new damage caused to the existing engine or damage to a replacement engine.**

 Hide Details

**Feedback Information**

Viewed: 1217

Helpful: 32

Not Helpful: 1

No Feedback Found

Copyright © 2013 Navistar, Inc.