

**NUMBER:** 02-002-13

**GROUP:** Front Suspension

**DATE:** April 04, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

#### SUBJECT:

Cold Weather Noise From Front End Over Bumps

#### **OVERVIEW:**

This bulletin involves replacing both left and right front jounce bumpers.

## **MODELS:**

2012- 2013 (FF)

**Fiat 500** 

NOTE: This bulletin applies to vehicles built prior to March 7, 2013 (MDH 0307XX).

## SYMPTOM/CONDITION:

The customer may experience a noise from the front of the vehicle while going over bumps which may be more noticeable in colder temperatures.

# **DIAGNOSIS:**

If the customer describes the symptom, perform the Repair Procedure.

#### PARTS REQUIRED:

Qty.	Part No.	Description
2	68073020AB	Bumper, Jounce - Front

#### REPAIR PROCEDURE:

- Remove and disassemble the left and right front strut assemblies. Refer to the detailed removal procedures available in DealerConnect>TechCONNECT> under: Service Info> 02 - Front Suspension> Front> STRUT, Suspension, Assembly> Removal/Disassembly.
- 2. Replace both left and right front jounce bumpers (4) (Fig. 1).

02-002-13 -2-




Fig. 1 Strut Disassembly

- 1 Strut Damper Assembly
- 2 Strut Damper Shaft
- 3 Coil Spring
- 4 Jounce Bumper
- 5-10 Upper Mount/Retainer and Dust Boot Assembly
- Reassemble and install the left and right front strut assemblies. Refer to the detailed removal procedures available in DealerConnect>TechCONNECT> under: Service Info> 02 - Front Suspension> Front> STRUT, Suspension, Assembly> Assembly/Installation.

NOTE: Verify wheel alignment is within specifications. (Refer to 02 - Front Suspension/Wheel Alignment - Standard Procedure/Specifications).

## **POLICY:**

Reimbursable within the provisions of the warranty.

#### TIME ALLOWANCE:

Labor Operation No:	Description	Amount
02-27-20-93	Replace Both Front Jounce Bumpers (2 - Skilled)	1.4 Hrs.

## **FAILURE CODE:**

ZZ Service Action	
-------------------	--