

SERVICE BULLETIN

Assification: Reference: Date:

EL13-015a NTB13-057a October 23, 2013

2013 - 2014 ALTIMA SEDAN; LANE DEPARTURE WARNING AND BLIND SPOT WARNING SYSTEMS SERVICE INFORMATION

This bulletin has been amended. Updates have been made on all pages. Please discard previous versions of this bulletin.

APPLIED VEHICLE: 2013 - 2014 Altima Sedan (L33) equipped with LDW and BSW

SERVICE INFORMATION

This bulletin contains supplemental diagnostic information related to 2013 and 2014 Altima Sedan equipped with the Lane Departure Warning (LDW) and Blind Spot Warning (BSW) systems.

Although the Electronic Service Manual (ESM) should be the primary source of information for inspection, Diagnosis, and repair, the Supplemental Diagnosis information in this bulletin will assist in these areas.

The information in this bulletin includes:

- What to check / inspect <u>first</u> when a BSW / LDW related warning is shown in the Vehicle Information Display
- What to check / inspect <u>first</u> when the BSW and/or LDW lights are flashing, and/or DTCs are stored
- Additional ITS Information that is helpful for system diagnostics.
- Possible error codes that may display on the navigation screen during "Affordable ITS Camera" calibration.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

LDW/BSW Supplemental Diagnosis

If a 2013 or 2014 Altima Sedan is presented with one or more of the following items, perform the Preliminary Checks on the next page.

 Message "Malfunction – See Owner's Manual" with LDW / BSW icons showing in the Vehicle Information Display (including but not limited to what shows in Figure 1)




Figure 1

- LDW / BSW lights to the left of the Vehicle Information Display are flashing
- LDW / BSW / MOD (Moving Object Detection) related DTCs are found stored
- LDW / BSW does not meet customer expectations (possibly related to environmental issues i.e. rain, etc.)

2/5 NTB13-057a

Preliminary Checks

- 1. Resolve DTCs for non ITS (Intelligent Technology Suite) first.
 - Issues with other systems may trip a BSW / LDW related DTC due to improper communication. Resolve the cause of any DTCs for other systems first. Once the non ITS DTCs are resolved, check for BSW / LDW related lights / DTCs again.
- 2. If DTC U1308 is stored; check the following possible causes:
 - Part(s) have been replaced:
 - > RR camera
 - > ITS controller
 - Disconnected / loose connections:
 - > RR camera
 - > ITS controller
 - > ITS switch
 - Wrong part installed (may show error 2 when calibrating):
 - > RR camera is not ITS camera
 - Dash switch
- 3. Refer to the Additional ITS Information on the next page for details that may help with diagnostics.
- 4. Continue diagnosis / repairs using the ESM.

3/5 NTB13-057a

Additional ITS Information

- IBA (Intelligent Brake Assist) light may turn ON if the ITS controller is disconnected.
- <u>ITS system is sensitive to heavy rains</u> and wet surfaces (this is stated in the Owner's Manual). Customer comments may state that the system is not working properly or note that the system shuts off when no objects exist.
 - Example: The camera unit detects reflected images of vehicles or roadside objects that are not actually in the detection zone, especially when the road is wet.
 - Refer to "BSW driving situations" in the "Starting and driving" section of the Owner's Manual.
- <u>LDW / BSW white icons in dash</u> will blink if the system is temporarily disabled. The
 "clean camera" message may also appear in the Vehicle Information Display.
 Normally, this is due to low washer fluid level. "Washer Fluid Low" warning will
 appear in the Vehicle Information Display.
 - If LDW / BSW white icons in dash blink and/or the "clean camera" message appears in the Vehicle Information Display and washer fluid is OK, test the washer pump related to the camera cleaning system located in the trunk. Other possible causes to check would be the pump ECU in the trunk and/or washer hoses, making sure fluid is properly getting to the camera cleaning system.
- <u>"Initialize Camera Image Calibration"</u> in CONSULT III plus: **Do not use this feature** unless instructed by NNA personnel i.e. TECH LINE, etc.
- When a NAVI system has been replaced, it is possible that ITS concern items may have been disconnected or triggered. Check for DTCs and if necessary, recalibrate the ITS system.

4/5

NTB13-057a

Possible Errors Codes for "Affordable ITS Camera" Calibration

The following error codes may display on the navigation screen during "Affordable ITS Camera" calibration.

IMPORTANT: In addition to the items listed under Possible Cause/Remedy, if any of the following errors display, re-measure and align targets, accurately place them again, and make sure the orientation of the targets is correct.

Error Code	Possible Cause / Remedy
Error 2	Wrong serial connection detected from rear camera / check for wrong part
Error 11	Center target is orientated incorrectly or out of position
Error 12	Left target marker not detected
Error 13	Left or right target or both orientated incorrectly or in the wrong position
Error 21	Center target marker is dirty / clean the target
Error 22	Left target marker is dirty / clean the target
Error 23	Right target marker is dirty. Targets are orientated correctly but in the wrong position / clean target, reposition
Error 51	Yaw angle error. Camera doesn't install normally or incorrect location of center target marker
Error 52	Position horizontal axis way is NG. Center Target is in the wrong position Pitch angle error. Camera doesn't install normally or location for center target marker position vertical axis way is NG. Targets are orientated incorrectly or in the wrong position
Error 53	Roll angle error. Camera doesn't install normally or location for left & right target markers are not positioned correctly

5/5

NTB13-057a