

TECHNICAL BULLETIN  
LTB00568NAS1  
25 OCT 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 309-00C / -00D**

**Exhaust Intermediate Pipe Repair**

**AFFECTED VEHICLE RANGE:**

**LR4 (LA)**

**Model Year:** 2010-2012  
**VIN:** AA510178-CA631180

**Range Rover Sport (LS)**

**Model Year:** 2010-2013  
**VIN:** AA212145-DA771200  
**Engine:** V8 5.0L Petrol

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** An air leak / 'hiss' noise may be heard from the rear, post-catalyst section of the exhaust intermediate pipe.

**Cause:** This may be caused by a weld separation.

**Action:** Should a customer express this concern, follow the Service Instruction outlined below.

**PARTS:**

LR050947 Exhaust pipe - LH - LR4, Range Rover Sport - 5.0L N/A Quantity: 1  
LR050948 Exhaust pipe - RH - LR4, Range Rover Sport - 5.0L N/A Quantity: 1

**TOOLS:**

Refer to Workshop Manual for any required special tools.

**WARRANTY:**

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Exhaust intermediate pipe repair - Single	<b>30.10.12</b>	0.4	42	LR021636
Exhaust intermediate pipe repair - Pair	<b>30.10.13</b>	0.6	42	LR021636

 **NOTE: Normal Warranty policies and procedures apply.**

**SERVICE INSTRUCTION:**

1. Carry out an exhaust intermediate pipe repair (see TOPIx Workshop Manual, Section 309-00C / 309-00D).