

TECHNICAL BULLETIN
LTB00588NAS1
04 OCT 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 204-06

Hydraulic Fluid 'Flow' or 'Hiss' Noise When Cornering

AFFECTED VEHICLE RANGE:

Range Rover Sport (LW)

Model Year: 2014 Onwards

VIN: EA300000 Onwards

Range Rover (LG)

Model Year: 2013 Onwards

VIN: DA001204 Onwards

MARKETS:

NAS

CONDITION SUMMARY:

Situation: On vehicles fitted with the Dynamic Response System **and** side steps (deployable and non-deployable) or fixed side tubes, a hydraulic fluid 'flow' or 'hiss' noise may be heard when the cornering.

Cause: This may be caused by the side steps contacting the Dynamic Response System pipes.

Action: Should a customer express concern, follow the Service Instruction outlined below.

PARTS:

LR052713 Rubber Insulator Quantity: 2

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**


| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART |
|---------------------------|----------|--------------|----------------|-------------|
| Install rubber insulators | 05.10.80 | 0.8 | 42 | LR035467 |

 **NOTE: Normal Warranty policies and procedures apply.**

SERVICE INSTRUCTION:


 **NOTE: Accessories-fitted side steps include Rubber Insulator, part number LR052713, in the fitting kit with updated fitting instructions.**

1. Remove the rear left rocker panel molding (see TOPIX Workshop Manual, Section 501-08).
2. Remove the left underbody molding.




E143121

3. Install rubber insulator at front bracket as shown.



E158942

4. Install rubber insulator at rear bracket as shown.



5. Install the left underbody molding.

- Tighten to nuts and bolts to 9 Nm.

6. Install the rear left rocker panel molding (see TOPIx Workshop Manual, Section 501-08).