

TECHNICAL BULLETIN
LTB00590NAS1
18 SEP 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 412-01

Climate Control System Odor

AFFECTED VEHICLE RANGE:

Range Rover Sport (LW)

Model Year: 2014 Onwards

VIN: EA300000 Onwards

Range Rover (LG)

Model Year: 2013 Onwards

VIN: DA001204 Onwards

MARKETS:

USA

CONDITION SUMMARY:

Situation: An odor may be present when the Climate Control System is switched 'ON'.

Cause: This may be caused by mold spore accumulation / build-up in the front evaporator core.

Action: Should a customer this express concern, follow the Service Instruction below.

PARTS:

LR056368	Evaporator	Quantity: 1
LR055993	Particle Filter	Quantity: 1

TOOLS:

No Tools Required

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Evaporator core - Renew - Range Rover Sport	82.25.20	6.6	42	LRO36365
Filter - Fresh air intake - Renew - Range Rover Sport	80.15.42	0.1	42	LRO36365
Evaporator core - Renew - Range Rover	82.25.20	7.1	42	LRO36365
Filter - Fresh air intake - Renew - Range Rover	80.15.42	0.1	42	LRO36365

NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1.  **NOTE: Prior to installation, wash out the evaporator core housing with warm water to remove any mold spore accumulation.**

Replace the front evaporator (see TOPIx Workshop Manual, Section 412-01).

2. Replace the particle filter (see TOPIx Workshop Manual, Section 412-01).