

TECHNICAL BULLETIN  
LTB00593NAS1  
23 SEP 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 412-03B / -03D**

Climate Control System Odor

**AFFECTED VEHICLE RANGE:**

**LR4 (LA)**

**Model Year:** 2012 Onwards

**VIN:** CA631053 Onwards

**Range Rover Sport (LS)**

**Model Year:** 2012-2013

**VIN:** CA758225-DA814822

**MARKETS:**

USA

**CONDITION SUMMARY:**

**Situation:** An odor may be present when the Climate Control System is switched 'ON'.

**Cause:** This may be caused by mold spore accumulation / build-up in the front evaporator core.

**Action:** Should a customer express this concern, follow the Service Instruction outlined below.

**PARTS:**

LR015350 Evaporator Quantity: 1

**TOOLS:**

No Tools Required

**WARRANTY:**

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Evaporator core - Renew - LR4	<b>82.25.20</b>	7.9	42	LR043353
Evaporator core - Renew - Range Rover Sport 5.0L N/A	<b>82.25.20</b>	7.8	42	LR043353
Evaporator core - Renew - Range Rover Sport 5.0L SC	<b>82.25.20</b>	7.6	42	LR043353

 **NOTE: Normal Warranty policies and procedures apply.**

**SERVICE INSTRUCTION:**

1.  **NOTE: Prior to installation, wash out the evaporator core housing with warm water to remove any mold spore accumulation.**

Replace the front evaporator core (see TOPIx Workshop Manual, Section 412-03B / 412-03D).