

TECHNICAL BULLETIN
Q341NAS1
23 OCT 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 303-14C / -14D

Service Action: Dynamic Oil Level Sensing

AFFECTED VEHICLE RANGE:

Range Rover (LG)
Model Year: 2013-2014
VIN: DA100519-EA124981

MARKETS:

NAS

CONDITION SUMMARY:

Situation: Vehicles within the listed VIN range may have an issue where the Instrument Cluster displays 'Engine oil level critically low' while driving even though the engine oil is at the correct level.

Action: Retailers are required to HOLD all affected vehicles in the above VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

No parts required

SPECIAL TOOLS:



NOTE: This document is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.

SDD with latest DVD and Calibration File; first available on DVD134.12 v.144

Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:



NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to the Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **Q341** together with the relevant Option Code from the table. The SRO and part information listed have been included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 October 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS	QTY. / VALUE
Q341	B	Update Engine Control Module software	12.90.13	0.2	-	1
Q341	C	Update Engine Control Module software Drive in/drive out	12.90.13 02.02.02	0.2 0.2	- -	- -



NOTE: Normal Warranty policies and procedures apply

SERVICE INSTRUCTION:

1.  **CAUTION: Ensure all ignition 'ON' / ignition 'OFF' requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.**



CAUTION: A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during SDD diagnosis / module programming.



NOTE: SDD must be loaded with DVD134.12 v.144 or later.

Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.



NOTE: The Engine Control Module (ECM) may also be known as Powertrain Control Module (PCM).

2. Turn ignition 'ON' (engine not running).
3. Connect the Symptom Driven Diagnostics (SDD) system to the vehicle and begin a new session.
4. Follow the SDD prompts.
5. Select 'Diagnosis' from the Session Type screen.
6. Select the 'Selected Symptoms' tab, and then select the following:
 - Electrical - Instruments - Information and message center - Message display area - Powertrain
7. Select 'continue'.

8. Select the 'Extras' tab.

9.  **NOTE: The Engine Control Module (ECM) may also be known as Powertrain Control Module (PCM).**

Select **Run** to perform the 'Configure existing module – Powertrain control module' option.

10. Follow all on-screen instructions to complete this task.

11. Exit the current session.

12. Disconnect the SDD and the battery power supply from the vehicle.