Audi

Technical Service Bulletin

19 Coolant leak at connection of water pump and hose leading to the heater core

19 13 40 2033491/2 June 17, 2013. Supersedes Technical Service Bulletin Group 19 number 13-36 dated April 15, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 cab, Q5, A6	2009-2013	All	2.0 TFSI

Condition

REVISION HISTORY			
Revision	Date	Purpose	
2	-	Revised Service (Part number for seal ring updated) Revised Required Parts and Tools (Part number for seal ring updated)	
1	04/15/2013	Initial publication	

Customer may report coolant leaking from the engine area.

Technical Background

The leak can be traced to the connection of the water pump and the hose leading to the heater core (Figure 1). The seal ring is not the cause of the leak.




Figure 1. Connection of water pump and hose leading to heater core

Audi

Technical Service Bulletin

Production Solution

Not applicable.

Service

- 1. Visually inspect the area of the suspected coolant leak.
- 2. Classify suspected coolant leak as Category 1, Category 2, or Category 3, according to the Categorization of Leaks table included in the Audi Warranty Policies and Procedures Manual (see below).

Categorization of leaks		Reimbursement of leaks	
The component (in this case, coolant hose) and the immediately adjacent component it is mounted to (in this case, the water pump)		With customer concern	Without customer concern
Category 1	may be wet with fluid residue, however, there is no droplet formation and no other components are affected.	Cleaning	No reimbursement
Category 2	is wet with fluid residue, and there is droplet formation or slight seepage, however, those droplets are not dropping off.	Cleaning	No reimbursement
Category 3	is wet with fluid residue, there is droplet formation, and those droplets are dropping off.	Replacement of leaking part	

If the leak falls into Category 1 or Category 2, proceed as instructed by the table. If the leak falls into Category 3, proceed to step 3.

- 3. After confirming that the leak is a category 3 leak, take a photograph of the leak (use leak talcum spray if necessary) and attach a printout of the photograph to your warranty paperwork.
- 4. Replace the water pump (06H121026CF), seal ring (WHT006407), and the hose to the heater core (06H121065D).



Replacing only the seal ring may not prevent the leak from reoccurring.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.			
Service Number:	1962			
Damage Code:	0050			
Labor Operations:	Coolant pump remove+reinstall	1950 1913	290 TU	
	Coolant hose remove+reinstall	1962 1950	10 TU	
Diagnostic Time:	GFF	No allowance	0 TU	
	Road test prior to service procedure	No allowance	0 TU	
	Road test after service procedure	0121 0004	10 TU	
	Technical diagnosis at dealer's discretion			
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)			
Claim Comment:	As per TSB #2033491/2			

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
06H121026CF	Water pump with cooling thermostat	1
06H121065D	Water tube	1
N 10405604	Oval hexagon socket head bolt	2
N 90686902	Spring clip	1
WHT006407	Seal ring	1

Please verify the correct parts needed with you parts department.

Audi

Technical Service Bulletin

Additional Information

The following repair procedures will be necessary to complete this procedure:

- Repair Manual>>Engine>>Engine Mechanical>>19 Cooling System>>Removal and Installation>>Coolant Pump
- Repair Manual>>Engine>>Engine Mechanical>>19 Cooling System>>Removal and Installation>>Small Coolant Pipe

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.