



#### 20 Pump nozzle cannot be inserted into fuel tank filler neck, vehicle cannot be refueled

20 13 26 2033836/1 May 15, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2013	All	2.0 TDI Engine

#### Condition

Customer states that the vehicle cannot be refueled due to difficulty with inserting the fuel pump nozzle into the filler neck.

## **Technical Background**

Beginning with MY2013, the filler necks of all A3 TDI vehicles are equipped with a misfueling guard (Figure 1). The guard minimizes the likelihood that fuel other than ultra-low sulfur diesel will be put into the vehicle.

The misfueling guard is designed to remain in a locked position when a nozzle with a diameter typically suited for non-diesel fuels (approximately 13/16", or 20.6mm) is inserted, to prevent further insertion of the nozzle into the filler neck.

A nozzle with a larger diameter typically suited for diesel fuel (approximately 15/16", or 23.8mm) will unlock the misfueling guard when inserted, allowing the nozzle to be further inserted into the filler neck.



Figure 1. Misfueling guard, indicated by red arrow.

# **Production Solution**

Not applicable.

Page 1 of 2

<sup>© 2013</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



### Service

Explain to the customer the purpose of the misfuel guard, and how the guard is designed to function.

Also state that some refueling stations may have damaged or worn nozzles with diameters that are out-ofspecification, and that such nozzles may not be able to unlock the misfueling guard. Suggest that in such cases, the customer try turning the nozzle before inserting it into the fuel filler neck, try using a different fuel pump, or see an authorized Audi dealer or authorized repair facility for assistance.

Do not replace the fuel tank, as this is a normal condition.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## **Additional Information**

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

<sup>© 2013</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.