



**NUMBER:** 08-048-13

**GROUP:** Electrical

**DATE:** June 28, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

**HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW**

**THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 13.04 OR HIGHER TO PERFORM THIS PROCEDURE.**

***SUBJECT:***

Flash: Coolant Gauge Reads Incorrectly Too High

***OVERVIEW:***

This Bulletin involves updating the Instrument Panel Cluster (IPC) software.

***MODELS:***

2013                      (DS)                                      Ram 1500 Pickup

**NOTE: This bulletin applies to vehicles built on or before March 22, 2013 (MDH 0322XX) equipped with 3.6 engines (sales code ERB) and Instrument Cluster W/Display Screen (sales code JAT).**

***SYMPTOM/CONDITION:***

A customer may note that the coolant temperature gauge looks like the engine temperature is high, the needle on the gauge will be at the 3/4 mark. On further inspection the technician will find the vehicle is running at normal temperature 228 to 230F/109-110C. After the cluster is updated the Temperature gauge will read at the 1/2 way mark, at normal operating temperature.

***DIAGNOSIS:***

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTC's are set. If DTCs are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Flash reprogram the Cluster. Help using the wiTECH Diagnostic Application for flashing the control modules is made available through the wiTECH Diagnostic Application. For instructions select the "HELP" tab on upper portion of the wiTECH window, then "HELP CONTENTS". This will open the Welcome to wiTECH Help screen where help topics can be selected.
2. Clear any DTC's that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-19-47-94	Module, Instrument Cluster (IC), Reprogram, (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

**FAILURE CODE:**

FM	Flash Module
----	--------------